



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Jan 2023, 11:37:38
Transaction Number	48465242 (CC10009)	Queue Number	655662



Chassis Number	JN1TANY62U0001480
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Patrol
Model Year	2011
Color	Black
Mileage	159124 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	Imported

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	LENS FADED	الاضاءة الرئيسية
01.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
02 Seats Condition		المقاعد
02.A Seat Condition	FRONT BOTH SIDE CRACKED & BOTH SIDE SEAT BACK COVER LOOSE	حالة المقاعد
03 Interior Condition		الحالة الداخليه
03.A AC Condition	NOT COOLING	المكيف
03.B Dash Board	CRACKED	لوحة القيادة
03.C Mirror	LEFT SIDE FOLDING NOT WORKING & LOOSE	المرايا
04 Suspension System		ممتص الصدمات
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
05 Body		جسم المركبة
05.A Fenders	FRONT LEFT SIDE REPAINTED , RIGHT SIDE BOTH REPAINTED PORTION REPAIRED & FRONT BOTH SIDE REFITTED	مدكار

DEFECT	REMARKS	
05.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
05.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
05.D Paint	BODY PORTION REPAINTED PORTION REPAIRED& MINOR DENT ,SCRATCHES	الصبغ
05.E Sign of side accident		وجود مؤشر لحادث في الجانب
05.F Bonnet	REPAINTED & REFITTED	غطاء المحرك
05.G Trunk	REPAINTED & REFITTED	صندوق
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
06.B Spare Tire &Tools	TIRE MISSING	الاطار الاحتياطي و العدة
06.C Front Tyre	BOTH SIDE 2019/2018 CRACKED	الاطار الامامي
07 Engine Condition		المحرك
07.A Visual Engine Condition	MINOR IL LEAK REFITTED	حالة المحرك النظري
07.B Smoke	WHITE SMOKE	دخان
07.C Mount	MOUNT RUBBER CRACKED	كرسي
08 Transmission Condition		الجير
08.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
08.B Visual Gear Box Condition	JERKING/REFITTED	حالة الجير النظري
08.C Road Test	NOT CHECK	فحص علي الطريق
09 Chassis Condition		الشاسي
09.A Chassis	CHASSIS FRAME RUST PROOFED PORTION RUSTY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Possession Certificate :	67038479
Chassis No :	JN1TANY62U0001480
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	159128 Kms.
Origin : Japan	Model Year : 2011
Gear Type : Automatic	Engine Size : 5600 CC
Engine No : NONE	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 3200 Kgs.	Empty 2300 Kgs.
	Weight :

Certificate Number :	5-TAS-2023-18586250		
Inspection Date :	18-01-2023		
Certificate Print Date :	18-01-2023		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	15 min 8 sec		
Appointment Ref Number :	--		
Start Time :	18:57	End Time :	19:12
Lane :	03	Token No. :	271
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)

10589 KM	1090 L	3783 AED	2.7 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 8 %	Service brake imbalance on rear axle 6 %	Parking brake imbalance between LHS and RHS 10 %	Vehicle on Petrol CO Reading 0.05 %
Vehicle on Petrol HC Reading 47 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	5	8	

Inspection Remarks:

chassis & under body components partly rusty REAR BACK PANEL & REAR CROSS MEMBER, LEFT SIDE QUARTER PANEL & WHEEL HOUSING REPAIRED, RAD SUPPORT FRAME REPAIRED(OLD HISTORY)

Payment Details

Inspection Performed by 6831 6831	Payment Method Cash	Transaction Number 18586250	Service Fees AED 170 Collected on 18/01/2023
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Shawkat Mohamed Samir

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

