

Queue Number 2767349

Transaction Date 19 Sep 2026, 12:58:37

Site Name
840 - Emirates AuctionsTransaction Number
27771033 (CC10021) (CC10021)

Vehicle Details

Chassis Number	MMEMC21XXH*****
Specification	GCC Specification
Make	Mitsubishi
Model	Montero
Model Year	2017
Color	Grey
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	BOTH LEFT SIDE REPAINTED,REPAIRED,REAR RIGHT SIDE PORTION DAMAGED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.E Bumper	MISALIGN,PORTION DAMAGED .	دعامية

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS FRAME MUDDY,GETTING RUSTY PORTION DENT / OK	الشاسيه
--------------	---	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	NOT CHECKED,PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	---------------------------------	----------------------

05.B Road Test	NOT CHECK	فحص علي الطريق
----------------	-----------	----------------

06 Tires and Rims Condition الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2021 WORN OUT CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE WORN OUT CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACK	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX COVER PORTION DAMAGED,INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C Door Panel	WORN OUT	لوحة بطانة الباب
09.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae