



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	13 Nov 2021, 18:02:01
Transaction Number	13242347 (CC10006)	Queue Number	312309



Chassis Number	JTEHJ09J275181624
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	2007
Color	Blue
Mileage	533248 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED	الصبغ
01.B Roof	ROOF PAINT FADED	السقف
01.C Pillars	INNER COVER LOOSE	القوائم
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Seat Belt	OK	حزام الأمان
02.B Seat Condition	SEAT COVER MODIFIED,PORTION WORNOUT&REAR SEAT MISSING	حالة المقاعد
<b>03 Interior Condition</b>		<b>الحالة الداخلية</b>
03.A Door Panel	DAMAGED &RELEATHER	لوحة بطانة الباب
03.B Dash Board	LOOSE	لوحة القيادة
03.C AC Condition	REAR NOT WORKING	المكيف
03.D Other	CONSOLE BOX LOOSE	اخرى
03.E Roof Light	LEFT MIDDLE ROOF HANDLE MISSING	أنارة السقف
03.F Sun Visor	LIGHT NOT WORKING	حاجب الشمس
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Tail Light	REAR LEFT SIDE CRACKED	الانارة

DEFECT	REMARKS	
04.B Head Light	LEFT BRACKET BROKEN	الاضاءة الرئيسية
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>06 Exhaust System</b>		<b>نظام العادم</b>
06.A Other	CATAYLIC CONVERTER MISSING & HEADRES MODIFIED	اخرى
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	REAR BOTH SIDE ARCH CHASSIS BULDGE	الشاسيه
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	,MINOR OIL LEAK,REFITIED	الجير
08.C Gear Box Mount	BUSHES CRACKED	كرسي الجير
<b>09 Engine Condition</b>		<b>المحرك</b>
09.A Engine Condition	REFITIED&TWO BOLT MISSING	حالة المحرك
09.B Mount	BUSHES CRACKED	كرسي
<b>10 Wipers and Arms</b>		<b>المساحات</b>
10.A Wiper Arm & Blade	WORNOUT	ازرع المساحات والشفرات
<b>11 Steering Condition</b>		<b>المقود</b>
11.A Steering Boot	BOOT CUT	ربلة المقود
11.B Steering Oil	OIL LEAK	زيت المقود
11.C Axel	BOOT CUT	اكسلات
11.D Tie Rod End	BOOT CUT	مؤخرة الرودادات
11.E Other	STABILIZER LINK BUSHES CRACKED	اخرى
<b>12 Suspension System</b>		<b>ممتص الصدمات</b>
12.A Ball Joint	BOOT CUT	مفصل كروي
<b>13 Brake Condition</b>		<b>الفرامل</b>
13.A Break Pads	BRAKE WEAK	سفايف الرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.



# Test Certificate



✓ PASS

Vehicle  
Registration



Plate Details :	T 27665 Dubai Private
Chassis No :	JTEHJ09J275181624
Vehicle Make :	TOYOTA
Vehicle Model :	LAND CRUISER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Blue
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	532670 Kms.
Origin : Japan	Model Year : 2007
Gear Type : Manual	Engine Size : 4500 CC
Engine No : 1FZ0770101	Horse Power : 323
Axles No : 2	Cylinders : 6
No Of Doors : 4	No Of Seats : 8
G. V. W. : 3095 Kgs.	Empty Weight : 2400 Kgs.

Certificate Number :	5-MUM-2021-15346517
Inspection Date :	30-10-2021
Certificate Print Date :	20-11-2021
Services :	Registration Test
Vehicle Testing Partner :	Al Mumayaz Vehicle Inspection
Vehicle Testing Center :	Al Mumayaz Al Mizhar
Total Time Taken :	7 min 59 sec
Appointment Ref Number :	--
Start Time : 16:40	End Time : 16:48
Lane : 02	Token No. : 223
Attempt : 1	Prints No : 3

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption ( Rate last 12 Months )

18958 KM	1951 L	3161 AED	4.7 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Vehicle on Petrol CO Reading 0.33 %	Vehicle on Petrol HC Reading 102 PPM VOL	Service brake imbalance on front axle 14 %	Service brake imbalance on rear axle 20 %
Parking brake imbalance between LHS and RHS 0 %			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	8	5	

## Inspection Remarks:

FRONT BUMPER FRAME,BULKHEAD,RADIATOR FRAME,FRONT BOTH SIDE FENDERS FRAME OLD REPAIRED,REAR LEFT SIDE CHASSIS MINOR BULGED.MINOR DENT,SCRATCHES ON BODY.CHANGE STEERING BOOT WORN OUT CHANGE FRONT AXLE BOOT WORN OUT

## Payment Details

Inspection Performed by 75215 MZ 89 MZ 89	Payment Method Cash	Transaction Number 15346517	Service Fees AED 170 Collected on 30/10/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Mohamed elbaily ali Abdellah

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

