



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>30 Aug 2022, 11:06:41</b>
Transaction Number	<b>26734239 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1GCEK14T76Z285214</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Silverado</b>
Model Year	<b>2006</b>
Color	<b>Brown</b>
Mileage	<b>295553 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Mount	MOUNT RUBBER CRACKED	كرسي
01.B Visual Engine Condition	OIL LEAK REFITED	حالة المحرك النظري
01.C Smoke	WHITE SMOKE	دخان
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A AC Condition	OK & GRILL DAMAGED	المكيف
02.B Dash Board	PORTION CRACKED	لوحة القيادة
02.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.D Door Panel	PORTION LOOSE	لوحة بطانة الباب
02.E Mirror	ADJUSTMENT NOT WORKING	المرابيا
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03.C Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM CONTROL BUSHES CUT	ازرع

DEFECT	REMARKS	
04.B Ball Joint	BOOT CUT	مفصل كروي
04.C Leaf Spring	BUSHES WORN OUT	
04.D Other	STABLIZER LINK BOOT CUT	اخرى
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	FRONT RIGHT SIDE BEND ,CHASSIS FRAME COMPLETELY THICK RUST PROOFED PORTION RUSTY ,	الشاسيه
05.B Chassis Number	VIN CHECKED ON WINDSHIELD , STICKER FADED	رقم القاعدة
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	OIL LEAK REFITTED	حالة الجير النظرى
06.B Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
06.C Road Test	NOT CHECKED	فحص علي الطريق
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Paint	BODY TOTALLY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES	الصبغ
07.B Floor	FLOOR PORTION BOTH SIDE RUNNING BOARD REPAIRED, THICK RUST PROOFED	الارضية
07.C Pillars	BOTH SIDE B/PILLAR OUTER REPAIRED REPAINTED	القوائم
<b>08 Exhaust System</b>		<b>نظام العادم</b>
08.A Modification	MODIFIED NOISY	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Possession Certificate :	66835145
Chassis No :	1GCEK14T76Z285214
Vehicle Make :	CHEVROLET
Vehicle Model :	SILVERADO
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Brown
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	295555 Kms.
Origin : United States	Model Year : 2006
Gear Type : Automatic	Engine Size : 6000 CC
Engine No : C6Z285214	Horse : --
Axles No : 2	Power :
No Of : 2	Cylinders : 8
Doors :	No Of Seats : 3
G. V. W. : 1800 Kgs.	Empty Weight : 1500 Kgs.

Certificate Number :	5-TAS-2022-17551668		
Inspection Date :	04-09-2022		
Certificate Print Date :	04-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	9 min 54 sec		
Appointment Ref Number :	--		
Start Time :	14:18	End Time :	14:28
Lane :	03	Token No. :	201
Attempt :	1	Prints No. :	1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption (Rate last 12 Months)

18460 KM	1900 L	6194 AED	4.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 18 %	Service brake imbalance on rear axle 27 %	Parking brake imbalance between LHS and RHS 22 %	Vehicle on Petrol CO Reading 0.53 %
Vehicle on Petrol HC Reading 70 PPM VOL			

## Inspection Remarks:

FRONT FENDERS , LEFT SIDE FENDER FRAME , RADIATOR FRAME & BULK HEAD , BUMPER FRAME REPAIRED , CHASSIS & UNDER BODY FLOOR MINOR RUSTY ,

## Payment Details

Inspection Performed by 6831	Payment Method VTP Credit Account	Transaction Number 17551668	Service Fees AED 170 Collected on 04/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.