



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>18 Jan 2023, 12:56:42</b>
Transaction Number	<b>68010100 (CC10010)</b>	Queue Number	<b>657693</b>



Chassis Number	<b>1N4AL11D55C307937</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Altima</b>
Model Year	<b>2005</b>
Color	<b>Grey</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED OIL LEAK	حالة المحرك النظري
<b>02 Interior Condition</b>		<b>الحالة الداخليه</b>
02.A Dash Board	PORTION DAMAGED & CONSOLE BOX COVER DAMAGED	لوحة القيادة
02.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.C AC Condition	NOT CHECK	المكيف
02.D Odometer reading	NOT CHECK	قراءة عداد المسافات
<b>03 Chassis Condition</b>		<b>الشاسي</b>
03.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED,DENT	الشاسيه
<b>04 Steering Condition</b>		<b>المقود</b>
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
04.B Steering Boot	BOOT CUT	ربلة المقود
04.C Steering Oil	OIL LEAK	زيت المقود
04.D Axle	BOOT CUT	اكسلات
<b>05 Body</b>		<b>جسم المركبة</b>

DEFECT	REMARKS	
05.A Bonnet	REFITTED	غطاء المحرك
05.B Floor	PORTION DENT	الارضية
05.C Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
05.D Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
05.E Fenders	FRONT REFITTED	مدكار
05.F Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES PORTION FADED,PORTION RUSTY	الصبغ
05.G Pillars	INNER COVER LOOSE	القوائم
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSH CRACKED	ازرع
06.B Shock Absorber	LEAK	ممتص الصدمات
06.C Ball Joint	BOOT CUT	مفصل كروي
06.D Other	STABILIZER LINK BOOT CUT	اخرى
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Visual Gear Box Condition	NOT CHECK,OIL LEAK REFITTED	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.