





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20381274	Plate Category	: PRIVATE
Transaction Date	: 27 JUL 2020 15:16:30	Plate Number	: 310080 EA
Queue Number	: 201229	Import Doc. Ref.	:
Chassis Number	: 2GKFL8E36F6310080	Manufacturer/Model	: GMC/TERRAIN
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: GOLDEN
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات LOWER CONTROL ARM & SWAY BAR STABILISER LINK ROD BOOTS CRACK
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي BRAKE ROTORS RUSTY
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية FRONT TIRES DOT 2015/ REAR TIRES DOT 2014 & 2015
04.07 - Rims		الرنجات MINOR SCRATCHES
05 Body		الهيكل
05.02 - Paint		الصيغ BODY SCRATCHES & DENTS
05.03 - Doors		الابواب BONNET REPLACED
05.08 - Chassis (Frame)		الشاصية FRONT BOTH SIDE MEMBERS REPAIRED
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي FRONT WINDSHIELD REPLACED
06 General Items		الاشياء العامة
06.02 - Wiper Arms		أذرع ماسحات الزجاج REAR WIPER MALFUNCTION
06.14 - Transmission Condition		حالة ناقل الحركة OIL LEAK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان OK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى 14903 KMS
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.23 - Air Bag Damaged		المخدة الهوائية لا تعمل CURTAIN AIRBAGS DEPLOYED & CUT
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني SERVICE STABILITRAK/ TPMS LIGHTS ON



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20381274	Plate Category	: PRIVATE
Transaction Date	: 27 JUL 2020 15:16:30	Plate Number	: 310080 EA
Queue Number	: 201229	Import Doc. Ref.	:
Chassis Number	: 2GKFL8E36F6310080	Manufacturer/Model	: GMC/TERRAIN
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: GOLDEN
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صدىغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p>		

Test Certificate



FAILED

Possession Certificate :	64450576		
Chassis No :	2GKFL8E36F6310080		
Vehicle Make :	GMC		
Vehicle Model :	TERRAIN		
Vehicle Class :	Light Vehicle		
Body Type :	STATION		
Fuel :	Benzene		
Color :	Golden		
Drive Direction :	--		
Dimensions : (H x W x L) :	-- x -- x --		
Current Odometer :	14906 Kms.		
Origin :	Canada	Model Year :	2015
Gear Type :	--	Engine Size :	4200 CC
Engine No :	KF6310080	Horse Power :	--
Axles No :	2	Cylinders :	6
No Of Doors :	4	No Of Seats :	5
G. V. W. :	2250 Kgs.	Empty Weight :	1888 Kgs.

Certificate Number :	5-TAS-2020-12274237		
Inspection Date :	04-08-2020		
Certificate Print Date :	04-08-2020		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Emirates Auction		
Total Time Taken :	12 min 31 sec		
Appointment Ref Number :	--		
Start Time :	16:05	End Time :	16:18
Lane :	01	Token No. :	17
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle 1%	Service brake imbalance on rear axle 7%	Parking brake imbalance between LHS and RHS 7%	Vehicle on Petrol CO Reading 2.22 %
Vehicle on Petrol HC Reading 244 PPM VOL			

Inspection Findings

Defects

Defects	Issue	Severity
Gear/Differential repair gear oil leaking	Oil leaking continuously	Major
Tire change all 4 tires old (0815)	Others (Major)	Major

Inspection Remarks:

FRONT LEFT SIDE CHASSIS MAIN JOINT OPEN REPAIRED & RIGHT SIDE CHASSIS REPAIRED HAVE PASS C.C.M REPORT W/O# 199973 (02-11-2019). FRONT BULK HEAD, RADIATOR SUPPORT, BULK HEAD, LEFT SIDE FENDER, INNER MEMBER, DOOR MEMBER, REINFORCEMENT & FIRE WALL REPAIRED.

Payment Details

Inspection Performed by 59460	Payment Method VTP Credit Account	Transaction Number 12274237	Service Fees AED 170 Collected on 04/08/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا

