

Queue Number

2899815

Transaction Date

22 Oct 2026, 17:00:57

Site Name

840 - Emirates Auctions

Transaction Number

74233173 (CC10013) (CC10019)



Vehicle Details

Chassis Number	JTFHX02PXP*****
Specification	GCC Specification
Make	Toyota
Model	Hiace
Model Year	2023
Color	White
Mileage	106109 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED .	الصبغ
01.B Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT MUDDY	الارضية
01.D Bumper	MISALIGN,COVER HOOK MISSING	دعامية
01.E Pillars	LEFT SIDE B/PILLAR ROCKER PANEL REPAIRED	القوائم
01.F Other	RADIATOR LOWER SUPPORT BEND	اخرى
01.G Trunk	LOGO MISSING	صندوق
01.H Sign of back accident	BACK PANEL DENT	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY / FRONT RIGHT SIDE LOWER EDGE MINOR DENT	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION CUT & REAR SEAT MISSING	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 WORN OUT	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	RIGHT SIDE CRACKED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Leaf Spring	MISALIGN , BUSHES DRY CRACK	ازرع
08.C Arms	ARM BUSHES DRY CRACK	
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	LEFT SIDE COVER MIRROR MISSING & CENTER MIRROR PORTION LOOSE	المرآيا
09.C AC Condition	OK	المكيف
09.D Audio	NOT WORKING	صوتيات
09.E Dash Board	PORTION WORN OUT	لوحة القيادة
09.F Roof Ceiling	PORTION LOOSE	بطانه السقف
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae