



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Nov 2022, 13:23:10
Transaction Number	19460729 (CC10010)	Queue Number	622209



Chassis Number	JTHBE5D22H5028835
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	IS 350
Model Year	2017
Color	Grey
Mileage	219460 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	REAR LOW AIR FLOW	المكيف
01.B Dash Board	PORTION DAMAGED	لوحة القيادة
01.C Mirror	AUTO FOLDING NOT WORKING	المرايا
01.D Roof Ceiling	LOOSE,REFITTED.	بطانه السقف
01.E Sunroof	INNER COVER TIGHT.	فتحت سقف
01.F Odometer reading	NOISY WHILE TURNING STEERING .	قراءة عداد المسافات
01.G Other	CENTER CONSOLE BOX INNER COVER MISSING & WARNING MESSAGE ON CLUSTER DISPLAY.	اخرى
01.H Sun Visor	GLASS LIGHT NOT WORKING	حاجب الشمس
01.I Roof Light	ALL LIGHT NOT WORKING .	أنارة السقف
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021, CRACKED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
03 Lights		الاضاءة
03.A Warning Light	WARNING LIGHTS ON IN DISPLAY	ضوء تحذير
03.B Revers Light	LEFT SIDE NOT WORKING	نور الرجوع للخلف

DEFECT	REMARKS	
03.C Head Light	HIGH BEAM NOT WORKING	الاضاءة الرئيسية
04 Body		جسم المركبة
04.A Pillars	BOTH SIDE DOOR PILLARS ROCKER PANEL RUNNING BOARD REPAIRED , NEED TO REMOVE PILLAR COVER ,BEEDING COVER ROCKER PANEL COVER FOR PROPER INSPECTION.(SUSPECT CUT ,RE-JOINT)	القوائم
04.B Sign of side accident		وجود مؤشر لحادث في الجانب
04.C Bonnet	OPEN CABLE LOOSE.	غطاء المحرك
04.D Roof	ROOF ,ROOF RAIL REPAIRED. NEED TO REMOVE SEELING COVER FOR PROPER INSPECTION. (SUSPECT CUT .)	السقف
04.E Sign of front accident		وجود مؤشر لحادث في المقدمة
04.F Sign of back accident		وجود مؤشر لحادث في الخلف
04.G Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER REPAIRED.	اخرى
04.H Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
05 Seats Condition		المقاعد
05.A Seat Condition	PORTION DAMAGED,DRIVER SEAT ABNORMAL NOISY.	حالة المقاعد
06 Chassis Condition		الشاسي
06.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED & BEND .	الشاسيه
07 Engine Condition		المحرك
07.A Smoke	WHITE SMOKE.	دخان
07.B Visual Engine Condition	OK	حالة المحرك النظري
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	OK	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق
09 Brake Condition		الفرامل
09.A Brake Pedal	WEAK & WARNING LIGHT ON ABS SYSTEM	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.



④ This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only), towards the above service.
 ③ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 ② هذه الشهادة حصرًا في المقاييس التي يدرجها بالبروز في المواصفات الفنية للسيارة وليس لها علاقة بوحدة جلد جلد السيارة هذه الشهادة حصرًا في المواصفات الفنية للسيارة وليس لها علاقة بوحدة جلد جلد السيارة هذه الشهادة حصرًا في المواصفات الفنية للسيارة وليس لها علاقة بوحدة جلد جلد السيارة
 This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

Payment Details	Inspection Performed by 33710	Payment Method Cash	Service Name Registration Test
Inspection Remarks:	FRONT BOTH SIDE CHASSIS REPAIRED DENT CCM OK W/O : 2022-11-10-6-FRONT RIGHT SIDE FIRE WALL AREA FENDER FRAME, RA PILLER , FLOORING RUNNING BOARD , REAR BOTH SIDE DOOR PILLER , REAR LEFT SIDE SUSPENSION MOUNTING AREA MINOR DENT, FRONT BULK HEAD RAD FRAME RD		

Inspection Remarks: FRONT BOTH SIDE CHASSIS REPAIRED DENT CCM OK W/O : 2022-11-10-6-FRONT RIGHT SIDE FIRE WALL AREA FENDER FRAME, RA PILLER , FLOORING RUNNING BOARD , REAR BOTH SIDE DOOR PILLER , REAR LEFT SIDE SUSPENSION MOUNTING AREA MINOR DENT, FRONT BULK HEAD RAD FRAME RD

Engine Different Engine Number	5000	No	Incorrect information about GCC specific Incorrect information about GCC specifications with No Document
Engine Size Discrepancy in Engine Size	2500	Yes	

Discrepancies	Old Value	New Value	Verified
Engine Different Engine Number	NIL	2GR8992020	Verified



Plate Details :	Chassis No : JTHB5D22H5028835	Vehicle Make : LEXUS	Vehicle Model : IS 350	Vehicle Class : Light Vehicle	Body Type : SALOON	Fuel : Benzene	Color : Gray	Drive Direction : --	Dimensions : (H x W x L) : -- x -- x --	Current Odometer : 219459 Kms.	Origin : Japan	Model Year : 2017	Engine Size : 5000 CC	Horse Power : 310	Cylinders : 6	No Of Seats : 5	Empty Weight : 1500 Kgs.	G. V. W. : 2500 Kgs.
Services :	Inspection Date : 10-11-2022	Certificate Print Date : 10-11-2022	Registration Test	Vehicle Testing Partner : Tasjeel	Vehicle Testing Center : Tasjeel Al Qusais	Total Time Taken : 4 min 53 sec	Appointment Ref : --	Number : --	Start : 21:04	Time : --	End Time : 21:09	Token No. : 648	Prints No. : 1	Lane : 05	Attempt : 2	Certificate Number : 5-TAS-2022-18072623		

