



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Dec 2021, 18:13:35
Transaction Number	53759595 (CC10006)	Queue Number	312309



Chassis Number	5TFRM5F15HX119173
Engine Number	
Vehicle Class	Heavy
Manufacturer	Toyota
Model	Tundra
Model Year	2017
Color	Red
Mileage	20685 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Air Bag	BOTH SIDE AIR BAG DAMAGED	وسائد هوائية
01.B Roof Ceiling	PORTION LOOSE	بطانه السقف
01.C AC Condition	OK	المكيف
01.D Mirror	CENTER MIRROR LOOSE	المرايا
02 Body		جسم المركبة
02.A Pillars	LEFT SIDE C/PILLAR ,ROCKER PANEL REPAIRED	القوائم
02.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
02.C Doors	LEFT SIDE BOTH DOOR PORTION REPAINTED,PORTION REPAIRED	أبواب
02.D Fenders	FRONT LEFT SIDE FENDER REPAINTED&REAR CARRIER BOX REPAINTED,PORTION REPAIRED	مدكار
02.E Trunk	REPAINTED,PORTION REPAIRED	صندوق
02.F Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS GETTING MINOR RUSTY	صدأ
02.G Sign of side accident		وجود مؤشر لحادث في الجانب
02.H Floor	BODY MOUNT MISALIGN	الارضية
03 Lights		الاضاءة

DEFECT	REMARKS	
03.A Tail Light	REAR RIGHT SIDE LENS BROKEN	الانارة
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2017 MINOR CRACKED	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2017/2018	الاطار الخلفي
04.C Rims Condition	RIMS HAVE MINOR SCRATCHES	حالة الجنوط
05 Wipers and Arms		المساحات
05.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
06 Seats Condition		المقاعد
06.A Seat Belt	OK	حزام الأمان
06.B Seat Condition	OK	حالة المقاعد
07 Chassis Condition		الشاسي
07.A Chassis	REAR BOTH SIDE MIDDLE CHASSIS HEATED REPAIRED&RIGHT SIDE LEAF SPRING MOUNT REPAIRED&MIDDLE OUTER MINOR DENT	الشاسيه
08 Engine Condition		المحرك
08.A Engine Condition	OK	حالة المحرك
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	OK	الجير
09.C Propeller Shaft	CENTER PROPELLER SHAFT BEARING RUBBER WORNOUT	ناقل الحركة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	X 23139 Dubai Private
Chassis No :	5TFRMSF15HX119173
Vehicle Make :	TOYOTA
Vehicle Model :	TUNDRA
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Red
Drive Direction :	Left Hand Side
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	33289 Kms.
Origin :	United States
Model Year :	2017
Gear Type :	Automatic
Engine Size :	4600 CC
Engine No :	nil
Horse Power :	310
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 2400 Kgs. 3175 Kgs.

Certificate Number :	5-TAS-2022-15826693
Inspection Date :	05-01-2022
Certificate Print Date :	05-01-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	10 min 30 sec
Appointment Ref Number :	--
Start Time :	15:18
End Time :	15:28
Lane :	02
Token No. :	168
Attempt :	1
Prints No :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

292 KM	31 L	51 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
3 %	7 %	5 %	0.49 %

Vehicle on Petrol HC

Reading
62 PPM VOL

Inspection Remarks:

LEFT SIDE B,C PILLAR,ROCKER PANEL,RUNNING BOARD,WHEEL ARCH REPAIRED. REAR LEFT SIDE CHASSIS TOP PORTION MINOR REPAIRED/END MINOR DENT, REAR RIGHT SIDE LEAF SPRING MOUNTING AREA REPAIRED.

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
33706	VTP Credit Account	15826693	AED 170 Collected on 05/01/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

