

TEST CERTIFICATE

Site Number Transaction Number **840-Emirates Auctions** 15062144 (CC10006)

Transaction Date

03 Jan 2022, 17:59:11

WDDGF7HB7DA863864

Queue Number

312309



Car

Vehicle Class Manufacturer

Mercedes

Model

C63S AMG

Model Year

2013

Color

Silver

Mileage

70371 Km

Fuel Type

Petrol

No. Of Cylinders

Specification

European Imported

DEFECT REMARKS

| 01 Body | | جسم المركبة |
|------------------------------|---|-----------------|
| 01.A Fenders | RIGHT SIDE BOTH REPAIRED , REPAINTED & LEFT SIDE BOTH PORTION REPAIRED, REPAINTED | مدکار |
| 01.B Doors | RIGHT SIDE BOTH REPAIRED , REPAINTED & LEFT SIDE BOTH PORTION REPAIRED, REPAINTED | أبواب |
| 01.C Paint | TOTALY REPAINTED EXCEPT ROOF & PORTION REPAIRED, MINOR DENT, SCRATCHES ON BODY | الصبغ |
| 01.D Bumper | REPAINTED | دعامية |
| 01.E Bonnet | PORTION REPAIRED & REPAINTED | غطاء المحرك |
| O1.F Trunk | REPAINTED | صندوق |
| 01.G Pillars | RIGHT SIDE C/PILLAR, ROCKER PANEL REPAIRED | القوائم |
| 01.H Fuel Tank | LEAKING | خزان الوقود |
| 02 Interior Condition | | الحاله الداخليه |

02.A AC Condition NOT COOLING & ADJUSTMENT MISSING المكيف **REAR PORTION DAMAGED & LOOSE** 02.B Roof Ceiling بطانه السقف 02.C Mirror BOTH SIDE FOLDING NOT WORKING المرايا **03 Tires and Rims Condition** الاطارات

03.A Front Tyre **BOTH SIDE 2020** الاطار الامامي

| DEFECT | REMARKS | |
|---------------------------|--------------------------|------------------------|
| 03.B Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 04 Engine Condition | | المحرك |
| 04.A Engine Condition | OIL LEAK | حالة المحرك |
| 05 Transmission Condition | | الجير |
| 05.A Propeller Shaft | RUBBER DAMAGED | ناقل الحركة |
| 05.B Gear Box | SIGN OF LEAK | الجير |
| 06 Steering Condition | | المقود |
| 06.A Axel | REAR BOOT CUT & LEAK | اكسلات |
| 06.B Other | STABILIZER LINK BOOT CUT | اخري |
| 07 Wipers and Arms | | المساحات |
| 07.A Wiper Arm &Blade | WORN OUT | ازرع المساحات والشفرات |
| 08 Exhaust System | | نظام العادم |
| 08.A Modification | MODIFIED & NOISY | تعديلات |
| 09 Suspension System | | ممتص الصدمات |
| 09.A Shock Absorber | BODY LEVEL LOW | ممتص الصدمات |
| 10 Chassis Condition | | الشاصي |
| 10.A Chassis | VISABLE AREA OK | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.