



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>31 Jul 2022, 13:46:28</b>
Transaction Number	<b>96822904 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTJBM7FX7C5048030</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Lexus</b>
Model	<b>GX 460</b>
Model Year	<b>2012</b>
Color	<b>White</b>
Mileage	<b>119092 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OK	حالة الجير النظرى
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.B Pillars	REAR RIGHT SIDE PILLAR OUTER PANEL REPAIRED, REPAINTED	القوائم
02.C Sign of side accident		وجود مؤشر لحادث في الجانب
02.D Sign of front accident		وجود مؤشر لحادث في المقدمة
02.E Rusty	UNDER BODY PARTS, SUSPENSION ,CHASSIS FRAME GETTING RUSTY	صدأ
02.F Other	FRONT FENDER FRAME, BUMPER FRAME, RADITOR SUPPORT ,RIGHT SIDE WHEEL ARCH REPAIRED	اخرى
02.G Fenders	FRONT BOTH SIDE , REAR RIGHT SIDE PORTION REPAIRED, REPAINTED, REFITTED	مدكار
02.H Doors	RIGHT SIDE BOTH PORTION REPAIRED , REPAINTED, REFITTED	أبواب
02.I Bonnet	PORTION REPAIRED,REPAINTED & REFITTED	غطاء المحرك

DEFECT	REMARKS	
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A Air Bag	DAMAGED	وسائد هوائية
03.B AC Condition	OK	المكيف
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOT SIDE 2019	الاطار الامامي
04.B Rear Tyre	BOT SIDE 2019	الاطار الخلفي
<b>05 Chassis Condition</b>		<b>الشاصي</b>
05.A Chassis	FRONT RIGHT SIDE CHASSIS & MIDDLE REPAIRED, INNER DENT	الشاصيه
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	LOWER ARM BUSH CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	--
Chassis No :	JTJBM7FX7C5048030
Vehicle Make :	LEXUS
Vehicle Model :	GX 460
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	191656 Kms.
Origin : Japan	Model Year : 2012
Gear Type : Automatic	Engine Size : 5000 CC
Engine No : NIL	Horse 305
Axles No : 2	Power :
No Of 5	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 3000 Kgs.	Empty 2406 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17277363		
Inspection Date :	26-07-2022		
Certificate Print Date :	26-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	7 min 34 sec		
Appointment Ref Number :	--		
Start Time :	12:50	End Time :	12:58
Lane :	03	Token No. :	142
Attempt :	1	Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

5264 KM	542 L	1702 AED	1.3 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 6 %	Service brake imbalance on rear axle 4 %	Parking brake imbalance between LHS and RHS 1 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 0 PPM VOL			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	5	7	
Engine Size Discrepancy in Engine Size	5000	4600	

Inspection Remarks: bulk head, fender frame, front right side chassis end repaired & middle minor dent. Minor dents scratches on body.

## Payment Details

Inspection Performed by 6831	Payment Method Cash	Transaction Number 17277363	Service Fees AED 170 Collected on 26/07/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

ⓘ This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

ⓘ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

