

Queue Number 2750343

Transaction Date 14 Sep 2026, 15:42:39

Site Name
840 - Emirates AuctionsTransaction Number
65390448 (CC10009) (CC10011)

Vehicle Details

Chassis Number	1N4AL3APXG*****
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2016
Color	Black
Mileage	179968 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED,FRONT MISALIGN REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	FRONT BOTH,REAR LEFT SIDE REPAINTED PORTION REPAIRED,FRONT LEFT REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.F Bonnet	REPAINTED,REFITTED	غطاء المحرك
01.G Trunk	REPAINTED PORTION REPAIRED REFITTED,SWITCH MELTED	صندوق
01.H Sign of front accident	BUMPER FRAME , FENDER FRAME , BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED INNER DETACHED HOLE RIGHT SIDE LOWER EDGE DENT, EXTENSION END MINOR DENT	الشاسية
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	COVER PORTION WORN OUT	حالة المقاعد
---------------------	------------------------	--------------

Condition	Remarks	الحالة
05 Exhaust System		نظام العادم
05.A Catalytic Converter	CUT REWELDED	دبة البيئة
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	PARTS REFITTED , PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظرية للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	RIGHT SIDE PORTION CRACK	الاضاءة الرئيسية
08.B Tail Light	LEFT SIDE SIGN OF CRACK	الضوء الخلفي
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
11 Interior Condition		الحالة الداخليه
11.A Other	CENTER CONSOLE BOX PANEL PORTION WORN OUT , INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
11.B Mirror	CENTER PORTION FADED	المرآيا
11.C AC Condition	OK,CENTER GRILL PANEL CHROME PORTION CRACK WORN OUT	المكيف
11.D Roof Light	PANEL LOOSE	أنارة السقف
11.E Roof Ceiling	REFITTED	بطانه السقف
11.F Door Panel	PORTION LOOSE WORN OUT	لوحة بطانة الباب
11.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.H Gear Shifting Lever	KNOB WORN OUT,SHIFT LOCK COVER MISSING	ذراع نقل السرعات
11.I Engine Start Button	WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae