

Queue Number 2848964

Transaction Date 08 Oct 2026, 16:49:57

Site Name
840 - Emirates AuctionsTransaction Number
81485130 (CC10026) (CC10026)

Vehicle Details

Chassis Number	1N4AL3AP5F*****
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2015
Color	White
Mileage	252350 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES , PORTION FADED GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PARTS MINOR DENT	الارضية
01.E Bumper	MISALIGN, DAMAGE FIX BY SCREW ,FRONT LOGO DAMAGE ,	دعامية
01.F Windshield	FRONT GLASS CRACK	زجاج
01.G Bonnet	MISALIGN , REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME , BULK HEAD MISSING , INNER FENDER FRAME , RADIATOR LOWER SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis Extension	REAR BUMPER FRAME , RIGHT SIDE EXTENSION END REPAIRED GETTING RUSTY	تمديدات الشاسي
02.B Chassis	FRONT LEFT SIDE CHASSIS OUTER SKIRT REPAIRED DENT , GETTING RUSTY	الشاسيه

03 Engine Condition

المحرك

03.A Mount	UPPER MOUNT RUBBER CUT	كرسي
03.B Other	AIR FILTER HOUSING PANEL PORTION LOOSE	اخرى
03.C Engine Visual Condition	PARTS REFITTED GETTING RUSTY SIGN OF OIL WET , SHAKING	الحالة النظرية للمحرك

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY SIGN OF OIL WET , MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 CRACK WORN OUT , RIGHT SIDE DAMAGE	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2025 RIGHT SIDE 2024 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS FADED , HIGH BEAM BOTH SIDE NOT WORKING	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CUT	ازرع
07.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
08 Interior Condition		الحالة الداخلية
08.A Other	CENTER CONSOLE BOX DAMAGE , INETERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
08.B Mirror	FRONT LEFT SIDE HOUSING DAMAGE , CENTER VIEW MIRROR FADED	المرآيا
08.C Dash Board	PORTION WORN OUT	لوحة القيادة
08.D Sun Visor	LEFT SIDE DAMAGE	حاجب الشمس
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Steering Wheel and control buttons	WORN OUT , HORN NOT WORKING	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	PORTION WORN OUT , SHIFTER LOCK COVER MISSING	ذراع نقل السرعات
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	TANK COVER MISSING & EMTY LEVEL	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on

لشكاوي والمقترحات يمكنك التواصل معنا عبر

