

03.A Door Panel

TEST CERTIFICATE

لوحة بطانة الباب

Site Number 840-Emirates Auctions Transaction Date 12 Jan 2022, 13:45:24

Transaction Number 46147438 (CC10006) Queue Number 312309



Chassis Number SCBFJ63W9DC082103

Engine Number

Vehicle Class Car

Manufacturer Bentley

Model Continental

Model Year 2013

Color White

Mileage **166978 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

| 01 Chassis Condition | | الشاصي |
|-----------------------|---|-----------------|
| 01.A Chassis Number | VIN NUMBER STICKER ON DOOR DAMAGED | رقم القاعدة |
| 01.B Chassis | FRONT RIGHT SIDE CHASSIS REPAIRED | الشاسيه |
| O2 Body | | جسم المركبة |
| 02.A Fenders | FRONT BOTH SIDE & REAR RIGHT SIDE PORTION REPAIRED, REPAINTED | مدكار |
| 02.B Doors | PORTION REPAIRED & REPAINTED | أبواب |
| 02.C Paint | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY | الصبغ |
| 02.D Floor | UNDER FLOOR PORTION DAMAGED | الارضية |
| 02.E Bumper | REPAINTED | دعامية |
| 02.F Other | FRONT FENDER FRAME, APRON ,RADITOR SUPPORT REPAIRED & BUMPER FRAME REPAIRED | اخري |
| 02.G Pillars | RIGHT SIDE DOOR PILLAR,ROCKER PANEL, FLOOR REPAIRED & BOTH SIDE C/PILLAR OUTER REPAIRED | القوائم |
| 02.H Bonnet | REPAINTED, SHOCK WEAK & REFITTED | غطاء المحرك |
| 03 Interior Condition | | الحاله الداخليه |

COVER LOOSE

| DEFECT | REMARKS | |
|-----------------------------|--------------------------------------|------------------------|
| 03.B AC Condition | ОК | المكيف |
| 03.C Mirror | ОК | المرايا |
| 04 Seats Condition | | المقاعد |
| 04.A Seat Condition | COVER LOOSE | حالة المقاعد |
| 04.B Other | RIGHT SIDE ADJUSTMENT BUTTON MISSING | اخري |
| 05 Wipers and Arms | | المساحات |
| 05.A Wiper Arm &Blade | WORN OUT | ازرع المساحات والشفرات |
| 06 Engine Condition | | المحرك |
| 06.A Engine Condition | OIL LEAK & REFITTED | حالة المحرك |
| 07 Transmission Condition | | الجير |
| 07.A Road Test | NOT CHECK | فحص علي الطريق |
| 07.B Gear Box | ОК | الجير |
| 08 Tires and Rims Condition | | الاطارات |
| 08.A Front Tyre | BOTH SIDE 2018 CRACKED | الاطار الامامي |
| 08.B Rear Tyre | BOTH SIDE 2018 CRACKED | الاطار الخلفي |
| 09 Lights | | الاضاءة |
| 09.A Head Light | ALL LIGHT WORKING | الاضاءة الرئيسية |
| 10 Suspension System | | ممتص الصدمات |
| 10.A Suspension Subframe | FRONT SUB FRAME REFITTED&MINOR DENT | |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









Plate Details: SCBFJ63W9DC082103 Chassis No : Vehicle Make: BENTLEY Vehicle Model: CONTINENTAL Vehicle Class: Light Vehicle **Body Type:** Coupe Fuel: Benzene Color: White **Drive Direction:** Left Hand Side Dimensions: (H x W x L) --x--x--**Current Odometer:** 166976 Kms. Origin: United King.. Model Year: 2013 Gear Type: Engine Size: 4000 CC Automatic Engine No: CMM003909 **Horse Power:** Axles No: Cylinders: No Of Doors: 2 No Of Seats: 4 G. V. W.: Empty Weight: 1600 Kgs. 2200 Kas

Certificate Number: 5-TAS-2021-15791682 Inspection Date: 30-12-2021 Certificate Print Date : 30-12-2021 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Qusais Total Time Taken: 8 min 38 sec Appointment Ref Number: --Start Time: 8:56 End Time: 9:04 Lane: Token No.: 111 Prints No: 1 Attempt: 1

Carbon footprint



Thank you! You are environment protector

Vehicle Consumption (last 12 Months)



15045 KM

Distance per

year

Fuel consumed per year



Fuel cost per vear

3.8 ton Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle

2 %

Service brake imbalance on rear axle

Parking brake imbalance between LHS and RHS

Vehicle on Petrol CO Reading 0.03 %

Vehicle on Petrol HC Reading 199 PPM VOL

Inspection Remarks: FRONT BULK HEAD, FENDER&RIGHT SIDE FRAME MEMBER, FLOORING REPAIRED HAVING CCM W/O 2021-12-29-8

Payment Details

Inspection Performed by 71097 **Parking Slot No**

Payment Method Cash **Service Name Registration Test**

Transaction Number 15791682 **Attempt**

Service Fees AED 170 Collected on 30/12/2021 Received by

Alia Marwan Saif Obaid Alzaabi

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. 🗸 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهةً المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة لإجراء معاملة واحدة فقط خلال .30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.