



## TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Jan 2022, 14:15:22
Transaction Number	32226867 (CC10006)	Queue Number	312309



Chassis Number	5N1AA08B56N728556
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Armada
Model Year	2006
Color	White
Mileage	394169 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
<b>01 Seats Condition</b>		المقاعد
01.A Seat Condition	SEAT HAVE EXTRA COVER	حالة المقاعد
<b>02 Interior Condition</b>		الحالة الداخليه
02.A Mirror	BOTH SIDE ADJUSTMENT NOT WORKING PROPERLY	المرايا
02.B Dash Board	DASHBOARD&CENTER CONSOLE BOX DAMAGED & HAVE EXTRA SWITCH&ONE SWITCH MISSING	لوحة القيادة
02.C Roof Light	ROOF CONSOLE BOX MISSING	أنارة السقف
02.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.E Power Window Switch	FRONT RIGHT SIDE & REAR BOTH SIDE NOT WORKING	مفتاح النافذه
02.F AC Condition	OK&GRILL DAMAGED	المكيف
<b>03 Lights</b>		الاضاءة
03.A Head Light	MINOR FADED	الاضاءة الرئيسية
03.B Fog light	BOTH SIDE LOOSE , LENS BROKEN , NOT WORKING	كشاف الضباب
03.C Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
<b>04 Steering Condition</b>		المقود
04.A Axel	FRONT AXLE BOOT CUT	اكسلات

DEFECT	REMARKS	
04.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
04.C Steering Oil	OIL LEAK&NOISY,WHEEL HARD	زيت المقود
04.D Steering Boot	BOOT CUT	ربلة المقود
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OIL LEAK,REFITTED	حالة المحرك النظرى
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	OIL LEAK,REFITTED,JERKING	حالة الجير النظرى
06.B Road Test	NOT CHECK	فحص علي الطريق
06.C DIFFERENTIAL	DIFFERENTIAL MOUNT BUSH CUT	الدفرنشيل
06.D Propeller Shaft	FRONT PROPELLER SHAFT MISSING	ناقل الحركة
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
07.B Front Tyre	BOTH SIDE 2018/2019 CRACKED	الاطار الامامي
07.C Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	FRONT LOWER ARM BUSH WORN OUT	ازرع
08.B Shock Absorber	FRONT & REAR RIGHT SIDE SHOCK ABSORBER MINOR OIL LEAK	ممتص الصدمات
<b>09 Body</b>		<b>جسم المركبة</b>
09.A Roof	ROOF PORTION RUSTY	السقف
09.B Trunk	NOT OPENING	صندوق
09.C Windshield	FRONT WINDSHIELD CRACKED	زجاج
09.D Paint	BODY TOTALY REPAINTED EXCEPT ROOF,TRUNK & PORTION REPAIRED	الصبغ
09.E Bumper	REPAINTED	دعامية
09.F Door Handle &Lock	FRONT LEFT SIDE OUTER HANDLE &FRONT RIGHT SIDE INNER HANDLE COVER MISSING	مقابض الأبواب والأقفال
<b>10 Brake Condition</b>		<b>الفرامل</b>
10.A Hand Brake	NOT WORKING	فرامل اليد
<b>11 Chassis Condition</b>		<b>الشاسي</b>
11.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.