



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Apr 2022, 14:46:39
Transaction Number	97508526 (CC10006)	Queue Number	312309



Chassis Number	1GNEK18K1SJ374889
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Tahoe
Model Year	1995
Color	Gold ochre
Mileage	227869 Miles
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Engine Condition		
		المحرك
01.A Visual Engine Condition	MINOR OIL LEAK , REFITTED, SHAKING	حالة المحرك النظرى
01.B Mount	MOUNT RUBBER CRACKED	كرسي
02 Transmission Condition		
		الجير
02.A Road Test	NOT CHECKED	فحص علي الطريق
02.B Visual Gear Box Condition	MINOR OIL LEAK REFITTED, JERKING	حالة الجير النظرى
02.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
03 Body		
		جسم المركبة
03.A Rusty	UNDER BODY SUSPENSION PARTS THICK RUST PROOFED	صدأ
03.B Paint	BODY TOTALLY REPAIRED , REPAINTED DENTS SCRATCHES ON BODY (VEHICLE COLOUR CHANGED FROM BLUE TO GOLDEN)	الصبغ
03.C Bumper	FRONT BUMPER FRAME MISING	دعامية
04 Chassis Condition		
		الشاصي
04.A Chassis	CHASSIS FRAME THICK RUST PROOFED , STILL GETTING RUSTY , FRONT RIGHT SIDE END MINOR DENT	الشاسيه
04.B Chassis Number	CHASSIS NUMBER CHECKED ON WINDSHILED ONLY ,	رقم القاعدة

DEFECT	REMARKS	
DOOR STICKER MISSING		
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
06 Interior Condition		الحاله الداخليه
06.A AC Condition	OK	المكيف
06.B Sun Visor	BOTH SIDE MISSING	حاجب الشمس
06.C Audio	(LCD) SCREEN MISSING	صوتيات
06.D Mirror	LEFT SIDE COVER CRACKED	المرايا
07 Brake Condition		الفرامل
07.A Brake Pedal	WEAK SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	1GNEK18K1S374889
Vehicle Make :	CHEVROLET
Vehicle Model :	TAHOE
Vehicle Class :	Light Vehicle
Body Type :	JEEP
Fuel :	Benzene
Color :	Golden
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	366721 Kms.
Origin : United States	Model Year : 1995
Gear Type : Automatic	Engine Size : 6600 CC
Engine No : NIL	Horse Power : 210
Axles No : 2	Cylinders : 8
No Of Doors : 2	No Of Seats : 5
G. V. W. : 2600 Kgs.	Empty Weight : 2121 Kgs.

Certificate Number :	5-TAS-2022-16704983
Inspection Date :	08-05-2022
Certificate Print Date :	08-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	13 min 24 sec
Appointment Ref Number :	--
Start Time : 9:12	End Time : 9:25
Lane : 01	Token No. : 133
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 9 %	Service brake imbalance on rear axle 49 %	Parking brake imbalance between LHS and RHS 81 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 2 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Parking brake imbalance between LHS and RHS	More than 60% imbalance between LHS and	Major
Battery fix bracket	Unsecure	Major
Handbrake cable and bracket	Defective handbrake	Major
Arm, mounting, bushes replace front both side suspension bushes & lower arm ball joints	Worn-out bushes	Major
Doors and Locks tail gate not opening	Not open/close properly	Major
Service brake imbalance on rear axle	More than 30% imbalance between LHS and RHS	Major

Inspection Remarks:

right side chassis old repaired, front bumper, ulk head, fender frame, both side chassis end repaired, chassis thick rust proofed.

Payment Details

Inspection Performed by 62439 34944	Payment Method Cash	Transaction Number 16704983	Service Fees AED 170 Collected on 08/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

