

|              |                         |                    |                              |
|--------------|-------------------------|--------------------|------------------------------|
| Queue Number | 1945712                 | Transaction Date   | 14 Nov 2025, 11:59:16        |
| Site Name    | 840 - Emirates Auctions | Transaction Number | 83939143 (CC10024) (CC10024) |



## Vehicle Details

|                   |                   |
|-------------------|-------------------|
| Chassis Number    | JT3HJ09J1Y*****   |
| Specification     | GCC Specification |
| Make              | Toyota            |
| Model             | Land Cruiser      |
| Model Year        | 2000              |
| Color             | Black             |
| Mileage           | N/A NA            |
| Fuel Type         | Petrol            |
| Transmission Type |                   |
| No. Of Cylinders  | 6                 |

| Condition | Remarks | الحالة |
|-----------|---------|--------|
|-----------|---------|--------|

| 01 Body                     | جسم المركبة                                                                                   |
|-----------------------------|-----------------------------------------------------------------------------------------------|
| 01.A Fenders                | FRONT FENDERS FRAME REPAIRED. مدكار                                                           |
| 01.B Paint                  | BODY PORTION REPAINTED,PORION REPAIRED,PORION FADED,PORION RUSTY, DENTS & SCRATCHES , الصبغ   |
| 01.C Rusty                  | UNDER FLOOR SUSPENSION PARTS GETTING RUSTY صدأ                                                |
| 01.D Floor                  | PORION DENTS. الارضية                                                                         |
| 01.E Bumper                 | MISALIGNED,PORION DAMAGE دعامية                                                               |
| 01.F Roof                   | BOTH SIDE ROOF RAIL REPAIRED. السقف                                                           |
| 01.G Bonnet                 | REFITTED ,MODIFIED. غطاء المحرك                                                               |
| 01.H Pillars                | BOTH SIDE DOORS PILLARS TOP AREA REPAIRED ,PORION RUSTY. القوائم                              |
| 01.I Trunk                  | NOT OPENT TAIL DOOR,NOT CHECKED صندوق                                                         |
| 01.J Sign of front accident | BUMPER FRAME ,BULK HEAD ,RADIATOR SUPPORT ,WHEEL HOUSING REPAIRED. وجود مؤشر لحادث في المقدمة |
| 01.K Sign of side accident  | REAR QUARTER PANELS ,WHEEL ARCH REPAIRED. وجود مؤشر لحادث في الجانب                           |
| 01.L Sign of back accident  | REAR COMPARTMENT PANEL REPAIRED. وجود مؤشر لحادث في الخلف                                     |

| 02 Chassis Condition | الشاسي                                                                                                       |
|----------------------|--------------------------------------------------------------------------------------------------------------|
| 02.A Chassis         | FRONT BOTH SIDE CHASSIS END ,BODY MOUNT BRACKET AREA REPAIRED & BEND/KNK.MIDDLE CHASSIS AREA BULGED. الشاسيه |

| 03 Engine Condition | المحرك       |
|---------------------|--------------|
| 03.A Mount          | CRACK. كرسبي |

| Condition                        | Remarks                                                                    | الحالة                           |
|----------------------------------|----------------------------------------------------------------------------|----------------------------------|
| 03.B Modification                | AIR FILTER AND INTAKE ASSEMBLY MODIFIED.                                   | تعديلات                          |
| 03.C Engine Visual Condition     | ENGINE NOT START ALL SYSTEM NOT CHECK,PARTS REFITEED,GTING RUSTY,OIL LEAK. | الحالة النظرية للمحرك            |
| <b>04 Seats Condition</b>        |                                                                            | <b>المقاعد</b>                   |
| 04.A Seat Condition              | PORTION DAMAGE ,REAR SEATS MISSING.                                        | حالة المقاعد                     |
| <b>05 Exhaust System</b>         |                                                                            | <b>نظام العادم</b>               |
| 05.A Modification                | EXHAUST MODIFIED WITH HEADERS                                              | تعديلات                          |
| 05.B Catalytic Converter         | MISSING.                                                                   | دبة البيئة                       |
| <b>06 Transmission Condition</b> |                                                                            | <b>الجير</b>                     |
| 06.A Gear Box Visual Condition   | NOT CHECKED,PARTS REFITTED ,OIL LEAK,PARTS GETTING RUSTY.                  | الحالة النظرية للجير             |
| 06.B Gear Box Mount              | MOUNT CRACK.                                                               | كرسي الجير                       |
| 06.C Propeller Shaft             | GETTING RUSTY.                                                             | ناقل الحركة                      |
| 06.D DIFFERENTIAL                | OIL LEAK,,REFITTED.                                                        | الدفرنشل                         |
| 06.E Road Test                   | NOT CHECKED.                                                               | فحص علي الطريق                   |
| <b>07 Lights</b>                 |                                                                            | <b>الاضاءة</b>                   |
| 07.A Head Light                  | LENS FADED ,ALL LIGHT NOT CHECKED                                          | الاضاءة الرئيسية                 |
| 07.B Tail Light                  | CRACK.                                                                     | الضوء الخلفي                     |
| <b>08 Suspension System</b>      |                                                                            | <b>ممتص الصدمات</b>              |
| 08.A Shock Absorber              | MOUNT CRACK.                                                               | ممتص الصدمات                     |
| 08.B Arms                        | BUSHES CRACK ,REAR RIGHT SIDE CONTROL ARM BEND                             | ازرع                             |
| 08.C Stabilizer Bar And Link Rod | BOOT CUT.                                                                  | عمود التوازن و مثبت عمود التوازن |
| <b>09 Steering Condition</b>     |                                                                            | <b>المقود</b>                    |
| 09.A Steering Oil                | LEAK.                                                                      | زيت المقود                       |
| 09.B Steering Boot               | CUT                                                                        | ربلة المقود                      |
| 09.C Tie Rod End                 | BOOT CUT.                                                                  | مؤخرة الروداد                    |
| 09.D Axle                        | FRONT BOHT AXLE SHAFT MISSING.                                             | اكسلات                           |
| <b>10 Interior Condition</b>     |                                                                            | <b>الحالة الداخليه</b>           |
| 10.A Other                       | INTERIOR PARTS RUSTY ,SIGN OF FLOODED.                                     | اخرى                             |
| 10.B AC Condition                | NOT CHECKED                                                                | المكيف                           |
| 10.C FFloor Matting              | PORTION DAMAGE,LOOSE                                                       | فرش الأرضيه                      |
| 10.D Dash Board                  | PORTION DAMAGE ,MELTED.                                                    | لوحة القيادة                     |
| 10.E Roof Ceiling                | PORTION LOOSE                                                              | بطانه السقف                      |
| 10.F Odometer reading            | NOT CHECKED, ODO METER CLUSTER BLACKED.                                    | قراءة عداد المسافات              |
| 10.G Door Panel                  | PORTION DAMAGE ,DIRTY.                                                     | لوحة بطانة الباب                 |
| 10.H Gear Shifting Lever         | KNOB DUST COVER WORN OUT.                                                  | ذراع نقل السرعات                 |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](https://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](https://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للسكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)