



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Oct 2021, 17:51:04
Transaction Number	48081472 (CC10006)	Queue Number	312309



Chassis Number	KMHWG81R4BU257865
Engine Number	
Vehicle Class	Heavy
Manufacturer	Hyundai
Model	H1
Model Year	2011
Color	White
Mileage	214351 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,BODY DENT,SCRATCHES	الصبغ
01.B Door Handle &Lock	LEFT SLIDING DOOR NOT CLOSE &RIGHT DOOR OUTER HANDLE &BOTH INNER HANDLE MISSING	مقابض الأبواب والأقفال
01.C Bumper	REPAINTED	دعامية
01.D Doors	RIGHT DOOR REPAINTED	أبواب
01.E Fenders	FRONT BOTH FENDER &REAR RIGHT FENDER REPAINTED,PORTION REPAIRED&FENDER REFITIED	مدكار
01.F Other	FRONT FENDER FRAME REPAIRED	اخرى
01.G Bonnet	REFITIED&OPENING HANDLE CABLE DAMAGED,MISSING &STAND MODIFIED	غطاء المحرك
01.H Trunk	REPAINTED,REPAIRED&NOT OPENING &INNER LOCK COVER MISSING	صندوق
01.I Rusty	UNDER BODY PART ,CHASSIS , GETTING MINOR RUSTY	صدأ
01.J Roof	RUSTY,DENT	السقف
02 Engine Condition		المحرك
02.A Smoke	WHITE SMOKE	دخان
02.B Engine Condition	OIL LEAK,VIBRATION , MISFIRE	حالة المحرك

DEFECT	REMARKS	
02.C Other	PART OPEN,REFITIED	اخرى
03 Seats Condition		المقاعد
03.A Seat Belt	OK	حزام الأمان
03.B Seat Condition	DAMAGED	حالة المقاعد
04 Wipers and Arms		المساحات
04.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
05 Steering Condition		المقود
05.A Other	STEERING WHEEL HARD &STEERING WHEEL WORNOUT	اخرى
05.B Steering Boot	BOOT CUT	ربلة المقود
05.C Steering Oil	OIL LEAK	زيت المقود
05.D Tie Rod End	BOTH SIDE BOOT DRY CRACK	مؤخرة الرودادات
06 Interior Condition		الحاله الداخليه
06.A AC Condition	NOT WORKING	المكيف
06.B Roof Ceiling	DIRTY	بطانه السقف
06.C Roof Light	MISSING	أنارة السقف
06.D Dash Board	DASHBOARD AREA DAMAGED	لوحة القيادة
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING MINOR RUSTY	دسك وطنابير الفرامل
07.B Hand Brake	NOT WORKING	فرامل اليد
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2020/2021	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Gear Box	OK	الجير
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT LOWER ARMS BUSHES WORNOUT	ازرع
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	LOSE &CAP MISSING	خزان التبريد
12 Chassis Condition		الشاصي
12.A Chassis	OK	الشاسيه
13 Lights		الاضاءة
13.A Tail Light	REAR LEFT NOT WORKING	الانارة



- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.