



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>31 Jul 2022, 13:46:26</b>
Transaction Number	<b>12010605 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1G1YY22G115119237</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Chevrolet</b>
Model	<b>Corvette</b>
Model Year	<b>2001</b>
Color	<b>Grey</b>
Mileage	<b>193392 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Audio	NOT WORKING	صوتيات
01.B AC Condition	LOW COOLING	المكيف
01.C Sun Visor	DAMAGED	حاجب الشمس
01.D Power Window Switch	MAIN SWITCH PANEL DAMAGED	مفتاح النافذه
01.E Steering Wheel and control buttons	STEERING HARD	عجلة القيادة وازرار التحكم
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
02.C Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDERE FLOOR METAL COVER, DUSTY . BOTH SIDE RUNNING BOARD REPAIRED	الارضية
03.B Paint	BODY TOTALLY DESIGNED BY FAIBER. PAINT CANNOT BE CHECKED	الصبغ
03.C Doors	REFITTED	أبواب

DEFECT	REMARKS	
03.D Bonnet	REFITTED	غطاء المحرك
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Smoke	WHITE SMOKE	دخان
04.B Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
04.C Mount	MOUNT RUBBER CRACKED	كرسي
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	FORNT BOTH SIDE CHASSIS END LOWER PORTION DENT	الشاسيه
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	BUSHES CRACKED	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
<b>09 Steering Condition</b>		<b>المقود</b>
09.A Steering Boot	BOOT CUT	ربلة المقود
09.B Steering Oil	MINOR OIL LEAK	زيت المقود
09.C Axel	BOOT LEAK	اكسلات
09.D Tie Rod End	BOOT CUT	مؤخرة الرودادت
<b>10 Lights</b>		<b>الاضاءة</b>
10.A Head Light	LENS FADED	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Change possession :	66703088
Chassis No :	1G1YY22G115119237
Vehicle Make :	CHEVROLET
Vehicle Model :	CORVETTE
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Gray
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	193392 Kms.
Origin : United States	Model Year : 2001
Gear Type : Automatic	Engine Size : 5700 CC
Engine No : NIL	Horse 345
Axles No : 2	Power :
No Of 2	Cylinders : 8
Doors :	No Of Seats : 2
G. V. W. : 1800 Kgs.	Empty 1200 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17342631		
Inspection Date :	04-08-2022		
Certificate Print Date :	04-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	10 min 51 sec		
Appointment Ref Number :	--		
Start Time :	14:05	End Time :	14:15
Lane :	02	Token No. :	188
Attempt :	1	Prints No :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
0 %	1 %	6 %	0.73 %

## Vehicle on Petrol HC Reading

203 PPM VOL

## Inspection Findings

Defects	Issue	Severity
Dip beams( Low Beams) headlight polish	Lens cracked, broken or faded	Major
Tire change all old	Date of manufactured tampered or expired	Major
Engine repair oil leak	Others (Major)	Major

Inspection Remarks: radiator frame repaired //

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
30544	VTP Credit Account	17342631	AED 170 Collected on 04/08/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.