

Queue Number 2891020

Transaction Date 21 Oct 2026, 16:01:28

Site Name
840 - Emirates AuctionsTransaction Number
84889784 (CC10009) (CC10025)

Vehicle Details

Chassis Number	WBAFP3107C*****
Specification	GCC Specification
Make	BMW
Model	523i
Model Year	2012
Color	Grey
Mileage	110272 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT BOTH SIDE & REAR RIGHT SIDE PORTION REPAINTED , REAR LEFT SIDE REPAINTED PORTION REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAINTED MINOR DENTS SCRATCHES , PORTION FADED	الصبغ
01.C Doors	PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION COVERED PORTION MINOR DENT	الارضية
01.F Bumper	MISALIGN SCRATCHES PART COVER MISSING	دعامية
01.G Trunk	REFITTED	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COVERED MUDDY OILY CHECKED VISIBLE AREA OK	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	OIL LEAK DRIPPING PARTS REFITTED SHAKING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	PORTION LOOSE	حالة المقاعد
---------------------	---------------	--------------

05 Transmission Condition الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	MINOR OIL LEAK PARTS REFITTED, MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 CRACK	الاطار الامامي
06.B Rear Tyre	RIGHT SIDE 2024 CRACK , LEFT SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	SWITCH PORTION CRACK MELTED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION LOOSE , RIGHT SIDE PORTION CRACK	الضوء الخلفي
07.C Fog light	LEFT SIDE MISSING , RIGHT SIDE LENS FADED	كشف الضباب
08 Brake Condition		الفرامل
08.A Hand Brake	SWITCH PORTION CRACK	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحالة الداخلية
10.A Other	REAR CONSOLE BOX COVER PORTION DAMAGED	اخرى
10.B Mirror	BOTH SIDE FOLDING NOT WORKING , RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY GLASS FADED	المرآيا
10.C AC Condition	OK , REAR GRILL PORTION DAMAGED	المكيف
10.D Audio	SCREEN FADED SCRATCHES	صوتيات
10.E Roof Ceiling	PORTION LOOSE	بطانة السقف
10.F Odometer reading	DISPLAY COVER PANEL PORTION CRACK MELTED	قراءة عداد المسافات
10.G Door Panel	WORN OUT MELTED	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae