

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 87708086 (CC10006) Transaction Date

28 Dec 2021, 17:52:50

Queue Number

312309



Chassis Number 1HGCS22738A600192

Engine Number

Vehicle Class Car

Manufacturer Honda

Model Accord

Model Year 2008

Color Red

Mileage **289063 Km**

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification

DEFECT REMARKS

O1 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY REPAINTED, REPAIRED EXCEPT ROOF REPAINTED & BODY MINOR DENT, SCRATCHES	الصبغ
01.C Doors	REPAIRED & REPAINTED	أبواب
01.D Bumper	REPAINTED	دعامية
01.E Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.F Trunk	REPAIRED & REPAINTED	صندوق
01.G Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخري
O1.H Floor	UNDER FLOOR RUST PROOFED	الارضية

O2 Interior Condition

المكيف	NOT COOLING	02.A AC Condition
المرايا	CENTER MIRROR FADED	02.B Mirror
مفتاح النافذه	LEFT SIDE NOT WORKING	02.C Power Window Switch
لوحة القياده	COVER LOOSE	02.D Dash Board
لوحة بطانة الباب	LOOSE	02.E Door Panel
فتحت سقف	NOT WORKING	02.F Sunroof

DEFECT	REMARKS	
02.G Steering Wheel and control buttons	COVER DAMAGED	عجلة القيادة وازرار التحكم
03 Lights		الاضاءة
03.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
03.B Head Light	LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
04 Engine Condition		المحرك
04.A Engine Condition	OIL LEAK & REFITTED	حالة المحرك
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Gear Box Mount	BUSHES CUT	كرسي الجير
05.C Gear Box	OIL LEAK	الجير
06 Chassis Condition		الشاصي
06.A Chassis	FRONT CHASSIS OILY MUDY VISABLE AREA OK	الشاسيه
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
08 Steering Condition		المقود
08.A Steering Oil	OIL LEAK	زيت المقود
09 Seats Condition		المقاعد
09.A Seat Condition	ОК	حالة المقاعد
10 Tires and Rims Condition		الاطارات
10.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
11 Suspension System		ممتص الصدمات
11.A Suspension Subframe	SUSPENTION SUB FRAME GETTING RUSTY & BOTH SIDE	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



BUSHES CRACKED

- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.