



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	08 Mar 2023, 08:34:08
Transaction Number	46118471 (CC10010)	Queue Number	683847



Chassis Number	SCBCR63WX6C032986
Engine Number	
Vehicle Class	Car
Manufacturer	Bentley
Model	Continental
Model Year	2006
Color	Grey
Mileage	73879 Km
Fuel Type	Petrol
No. Of Cylinders	12
Specification	Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Bumper	MISALIGN ,FRONT PORTION CRACKED.FRONT GRILL LOOSE.	دعامية
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES ON BODY	الصبغ
01.C Sign of front accident		وجود مؤشر لحادث في المقدمة
01.D Door Handle &Lock	RIGHT SIDE OUTER DOOR HANDLE CHROME& LEFT SIDE LOCK COVER MISSING	مقابض الأبواب والأقفال
01.E Bonnet	SHOCK WEAK	غطاء المحرك
01.F Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY.	صدأ
01.G Other	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT REPAIRED.LOWER SUPPORT DENT .	اخرى
01.H Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED,REFITTED	مدكار
01.I Trunk	REFITTED,STAY SHOCK WEAK.	صندوق
01.J Floor	FLOOR ,REINFORCEMENT ,RUNNING BOARD DENT . SEELING RUBBER MISSING.	الارضية
02 Engine Condition		المحرك
02.A Visual Engine Condition	REFITTED. OIL LEAK , OIL FILTER AREA REPAIRED,MISFIRING ,ABNORMAL NOISY.	حالة المحرك النظري
03 Exhaust System		نظام العادم

DEFECT	REMARKS	
03.A Other	DENT .	اخرى
04 Chassis Condition		الشاسي
04.A Chassis Number	VIN STICKER REFITTED .VIN PLATE FADED.	رقم القاعدة
04.B Chassis	FRONT RIGHT SIDE CHASSIS END EDGE MINOR DENT	الشاسيه
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2020 INNER WORN OUT .	الاطار الامامي
06 Engine Cooling System		نظام تبريد المحرك
06.A Radiator Condition	FRONT CONDENSOR BEND .	حالة المبرد
07 Interior Condition		الحاله الداخليه
07.A AC Condition	OK	المكيف
07.B Roof Ceiling	LOOSE	بطانه السقف
07.C Steering Wheel and control buttons	PLAY.	عجلة القيادة وازرار التحكم
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	REFITTED ,OIL SUMP DENT .	حالة الجير النظري
08.B Road Test	NOT CHECK	فحص علي الطريق
09 Suspension System		ممتص الصدمات
09.A Suspension Subframe	BRACKET DENT .	
10 Lights		الاضاءة
10.A Warning Light	WARNING LIGHT ON IN CLUSTER.	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Possession Certificate :	67431990
Chassis No :	SCBCR63WX6C032986
Vehicle Make :	BENTLEY
Vehicle Model :	CONTINENTAL
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	73880 Kms.
Origin : United Kingd...	Model Year : 2006
Gear Type : Automatic	Engine Size : 6000 CC
Engine No : NIL	Horse 552
Axles No : 2	Power :
No Of 2	Cylinders : 12
Doors :	No Of Seats : 4
G. V. W. : 2300 Kgs.	Empty 1800 Kgs.
	Weight :

Certificate Number :	5-TAS-2023-19002792		
Inspection Date :	11-03-2023		
Certificate Print Date :	11-03-2023		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	11 min 54 sec		
Appointment Ref Number :	--		
Start Time :	13:12	End Time :	13:24
Lane :	02	Token No. :	156
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)

1288 KM	133 L	458 AED	0.4 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 7 %	Service brake imbalance on rear axle 2 %	Parking brake imbalance between LHS and RHS 1 %	Vehicle on Petrol CO Reading 0.06 %
Vehicle on Petrol HC Reading 67 PPM VOL			

Inspection Remarks: body minor scratches /engine minor oil leak/front right fender frame dent/front bumper misalign

Payment Details

Inspection Performed by 30544 6831	Payment Method VTP Credit Account	Transaction Number 19002792	Service Fees AED 170 Collected on 11/03/2023
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لتي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

