



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	07 Aug 2022, 13:41:03
Transaction Number	92713115 (CC10006)	Queue Number	312309



Chassis Number	JTFPX22PXD0044813
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Hiace
Model Year	2013
Color	White
Mileage	247125 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALY REPINTE PORTION REPAIRED MINOR DENTS SCRATCHES , PORTION FADED	الصبغ
01.B Sign of side accident		وجود مؤشر لحادث في الجانب
01.C Sign of back accident		وجود مؤشر لحادث في الخلف
01.D Floor	LEFT SIDE RUNNING BOARD,ROCKER PANEL,WHEEL ARCH REPAIRED & UNDER FLOOR THICK RUST PROOFED	الارضية
01.E Other	FRONT LEFT SIDE FENDER SPORT , REAR CROSS MEMBER REPAIRED	اخرى
02 Interior Condition		الحالة الداخلية
02.A AC Condition	LOW AIR FLOW & GRILL DAMAGED	المكيف
02.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.C Other	GEAR SHIFTING LEVER DUST COVER PORTION DAMAGED	اخرى
03 Seats Condition		المقاعد
03.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
04.B Visual Gear Box Condition	MINOR OIL LEAK & REFITTED	حالة الجير النظرى
04.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	BOTH SIDE 2020/2021	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2021 , LEFT SIDE WORN OUT	الاطار الامامي
06 Chassis Condition		الشاسي
06.A Chassis	FRONT LEFT SIDE CHASSIS OUTER REPAIRED	الشاسيه
07 Engine Condition		المحرك
07.A Visual Engine Condition	MINOR OIL LEAK & REFITTED	حالة المحرك النظرى
07.B Mount	MOUNT RUBBER CRACKED	كرسي
08 Steering Condition		المقود
08.A Steering Oil	MINOR OIL LEAK	زيت المقود
08.B Tie Rod End	BOOT CUT	مؤخرة الرودادت
08.C Steering Boot	BOOT CUT	ربلة المقود
09 Suspension System		ممتص الصدمات
09.A Ball Joint	BOOT CUT	مفصل كروي
09.B Arms	LOWER ARM BUSHES CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	JTFPX22PXD0044813
Vehicle Make :	TOYOTA
Vehicle Model :	HIACE
Vehicle Class :	Light Vehicle
Body Type :	VAN
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	247125 Kms.
Origin : Japan	Model Year : 2013
Gear Type : Manual	Engine Size : 2700 CC
Engine No : 2TR8583344	Horse 125
Axles No : 2	Power :
No Of 5	Cylinders : 4
Doors :	No Of Seats : 3
G. V. W. : 2700 Kgs.	Empty 1500 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17373686
Inspection Date :	09-08-2022
Certificate Print Date :	10-08-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Warsan
Total Time Taken :	11 min 11 sec
Appointment Ref Number :	--
Start Time : 13:48	End Time : 13:59
Lane : 05	Token No. : 754
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 10 %	Service brake imbalance on rear axle 11 %	Parking brake imbalance between LHS and RHS 14 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 6 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Reversing lamps REPAIR	Defective	Major
Spare Tire REPAIR	Puncture (Major)	Major
Vehicle Floor FIX ALUMINIUM SHIELD REAR COMPARTMENT	Others (Major)	Major
Shock Absorber CHANGE FRONT BOTH SIDE LEAK	Major leak	Major
Tire CHANGE FRONT LEFT	Uneven wear	Major
Dubai Municipality BRING FOOD WATCH ALL DOCUMENT	No document from authority	Major
Weight and Capacity Sticker FIX BOTH SIDE	Not available on both front doors	Major

Discrepancies	Old Value	New Value	Verified
Description - Registration Incorrect Vehicle Description	VAN	VAN WITH FRIDGE	

Inspection Remarks:

FRONT LEFT SIDE CHASSIS OUTER RUNNING BOARD FENDER FRAME REAR BACK PANE QURTER PANEL REPAIRED //

Payment Details

Inspection Performed by 34321	Payment Method VTP Credit Account	Transaction Number 17373686	Service Fees AED 170 Collected on 10/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Abdeirahman Mohammed Eltom Musa

i This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.



❗ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.