



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Oct 2021, 17:10:56
Transaction Number	88537162 (CC10006)	Queue Number	312309



Chassis Number	KMHCT41D6FU772531
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Accent
Model Year	2015
Color	White
Mileage	152137 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED	الصبغ
01.B Trunk	REPAIRED,REPAINTED,PAINT CRACKED,REFITIED,MISALIGN	صندوق
01.C Floor	REAR COMPARTMENT ,QUATAR PANEL BACK PANEL REPAIRED	الارضية
01.D Door Handle &Lock	FRONT LEFT OUTER HANDLE NOT WORKING PROPERLY &INNER COVER MISSING	مقابض الأبواب والأقفال
01.E Pillars	FRONT LEFT A/PILLAR POST&RUNNING BOARD REPAIRED&RUNNING BOARD STILL BEND &CRACKED	القوائم
01.F Bumper	REPAINTED,MISALIGN ,LOSE	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	REAR CHASSIS EXTENSION REPAIRED&CHASSIS &EXTENSION STILL BEND	الشاسيه
03 Lights		الاضاءة
03.A Indicator & Hazard light	FRONT NOT WORKING	الاشارات
03.B Head Light	FADED	الاضاءة الرئيسية
03.C Tail Light	REAR LEFT LENS MINOR FADED	الانارة
04 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
04.A Front Tyre	BOTH SIDE 2019 CRACKED & WORN OUT	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2015/2016 CRACKED & EXPIRED	الاطار الخلفي
05 Engine Condition		المحرك
05.A Engine Condition	OK	حالة المحرك
06 Transmission Condition		الجير
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Gear Box	OK	الجير
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
08 Suspension System		ممتص الصدمات
08.A Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
09 Interior Condition		الحالة الداخليه
09.A AC Condition	NOT WORKING	المكيف
09.B Mirror	LOSE	المرايا
10 Steering Condition		المقود
10.A Other	STEERING COLUMN,COUPLING CHECK LOSE	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	KMHCT41D6FU772531
Vehicle Make :	HYUNDAI
Vehicle Model :	ACCENT
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	152138 Kms.
Origin :	South Korea
Model Year :	2015
Gear Type :	--
Engine Size :	2000 CC
Engine No :	G4FCEU417...
Horse Power :	--
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	4
G. V. W. :	Empty Weight : 1500 Kgs. 1900 Kgs.

Certificate Number :	5-TAS-2021-15293968
Inspection Date :	23-10-2021
Certificate Print Date :	23-10-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	11 min 54 sec
Appointment Ref Number :	--
Start Time :	17:28
End Time :	17:39
Lane :	02
Token No. :	224
Attempt :	1
Prints No :	1

Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 1 %	Parking brake imbalance between LHS and RHS 11 %	Vehicle on Petrol CO Reading 0.29 %
Vehicle on Petrol HC Reading 95 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Stop lamps BRAKE LIGHT NOT WORKING	Defective	Major
Battery fix bracket	Unsecure	Major
Tire change all tire wornout & cracked	Worn out tread tire	Major
Dip beams(Low Beams) headlight clean right side ,lens faded	Lens cracked, broken or faded	Major
Spare Tire	Puncture (Major)	Major
Warning triangle	Missing	Major
Park and Tail lamps front right & rear left park light not working	Defective	Major
Reversing lamps reverse light not working	Defective	Major

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	4	5	

Inspection Remarks:

REAR LEFT SIDE MEMBER REPAIRED/ BULGED /BACK PANEL & SPARE TIRE HOUSING /REAR LEFT QUARTER PANEL/BOTH RUNNING BOARD/FRONT LEFT FENDER/BONNET REPAIRED

Payment Details

Inspection Performed by 62424	Payment Method Cash	Transaction Number 15293968	Service Fees AED 170 Collected on 23/10/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- i** This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- i** Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.



تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.