

Queue Number

2838174

Transaction Date

06 Oct 2026, 15:46:51

Site Name

840 - Emirates Auctions

Transaction Number

96315526 (CC10013) (CC10025)



Vehicle Details

Chassis Number	JTMHX05J6F*****
Specification	GCC Specification
Make	Toyota
Model	Land Cruiser
Model Year	2015
Color	White
Mileage	449404 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR BOTH SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION FADED	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK / LOWER SUPPORT RUSTY HOLE WEAK	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Roof	CARRIER PART MISSING	السقف
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	AUTO NOT WORKING	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME GETTING RUSTY DIRTY & BULGED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--------------------------------	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	REAR PORTION LOOSE	حالة المقاعد
---------------------	--------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY , HOUSING BOLT MISSING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
05.C Four Wheel Drive	NOT ENGAGED	الدفع الرباعي
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES / HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	WASHER PORTION DAMAGED , LEFT SIDE LENS FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE PORTION CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.D Fog light	NOT WORKING	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Ball Joint	BOOT CUT	مفصل كروي
09 Steering Condition		المقود
09.A Steering Boot	BOOT CUT LEAK	ربلة المقود
10 Interior Condition		الحالة الداخلية
10.A Other	CENTER CONSOLE BOX COVER PORTION LOOSE , INTERIOR PARTS GETTING RUSTY (SIGN OF FLOODED)	اخرى
10.B Mirror	BOTH SIDE FOLDING NOT WORKING , LEFT SIDE ADJUSTMENT NOT WORKING , RIGHT SIDE NOT WORKING PROPERLY LOOSE	المرآيا
10.C AC Condition	OK , REAR COVER PANEL PORTION DAMAGED GRILL PORTION LOOSE	المكيف
10.D Audio	SCREEN FADED	صوتيات
10.E Dash Board	WORN OUT	لوحة القيادة
10.F Roof Ceiling	PORTION CUT	بطانه السقف
10.G Sun Visor	LEFT SIDE BRACKET PORTION DAMAGED , RIGHT SIDE LIGHT COVER MISSING	حاجب الشمس
10.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
10.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae