



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 29 Jul 2022, 11:03:14 |
| Transaction Number | 86996914 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | 5TDBY68A7DS074486 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Toyota |
| Model | Sequoia |
| Model Year | 2013 |
| Color | Silver |
| Mileage | 331544 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|------------------------------------|--|----------------------------|
| 01 Body | | جسم المركبة |
| 01.A Paint | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES | الصبغ |
| 01.B Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 01.C Doors | FRONT RIGHT SIDE PORTION REPAINTED & REAR RIGHT SIDE PORION REPAIRED,REPAINTED | أبواب |
| 01.D Other | FRONT BUMPER FRAME BULK HEAF FENDER FRAME RADIATOR SUPPORT REPAIRED | اخرى |
| 01.E Bonnet | PORTION REPAIRED,REPAINTED & REFITTED | غطاء المحرك |
| 01.F Fenders | FRONT LEFT SIDE REPAIRED,REPAINTED,RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED & FRONT REFITTED | مدكار |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Front Tyre | BOTH SIDE 2019 CRACKED | الاطار الامامي |
| 02.B Rear Tyre | BOTH SIDE 2018 & CRACKED | الاطار الخلفي |
| 03 Suspension System | | ممتص الصدمات |
| 03.A Ball Joint | BOOT CUT | مفصل كروي |
| 03.B Arms | FRONT LOWER ARM BUSH CRACKED | ازرع |
| 03.C Shock Absorber | FRONT LEAK | ممتص الصدمات |

| DEFECT | REMARKS | |
|----------------------------------|---|------------------------|
| 03.D Other | STABILIZER LINK BOOT CUT | اخرى |
| 04 Engine Condition | | المحرك |
| 04.A Visual Engine Condition | MINOR OIL LEAK & REFITTED | حالة المحرك النظرى |
| 04.B Mount | MOUNT RUBBER CRACKED | كرسي |
| 04.C Smoke | WHITE SMOKE | دخان |
| 05 Chassis Condition | | الشاسي |
| 05.A Chassis | FRONT LEFT SIDE CHASSIS END REPAIRED SUSPECT REPLACED | الشاسيه |
| 06 Transmission Condition | | الجير |
| 06.A Visual Gear Box Condition | MINOR OIL LEAK & REFITTED | حالة الجير النظرى |
| 06.B Road Test | NOT CHECK | فحص علي الطريق |
| 06.C Gear Box Mount | MOUNT RUBBER CRACKED | كرسي الجير |
| 07 Seats Condition | | المقاعد |
| 07.A Seat Belt | REAR LEFT SIDE NOT WORKING | حزام الأمان |
| 08 Interior Condition | | الحاله الداخليه |
| 08.A AC Condition | OK | المكيف |
| 08.B Dash Board | PORTION CRACKED | لوحة القيادة |
| 09 Lights | | الاضاءة |
| 09.A Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



✓ PASS

| | |
|--------------------------|--------------------------|
| Plate Details : | T 77267 Dubai Private |
| Chassis No : | 5TDBY68A7DS074486 |
| Vehicle Make : | TOYOTA |
| Vehicle Model : | SEQUOIA |
| Vehicle Class : | Light Vehicle |
| Body Type : | STATION |
| Fuel : | Benzene |
| Color : | Silver |
| Drive Direction : | Left Hand Side |
| Dimensions : (H x W x L) | -- x -- x -- |
| Current Odometer : | 331527 Kms. |
| Origin : United States | Model Year : 2013 |
| Gear Type : Automatic | Engine Size : 5700 CC |
| Engine No : 3UR 5661173 | Horse 418 |
| Axles No : 2 | Power : |
| No Of 5 | Cylinders : 8 |
| Doors : | No Of Seats : 8 |
| G. V. W. : 2900 Kgs. | Empty Weight : 2200 Kgs. |

| | | | |
|---------------------------|---------------------|--------------|-------|
| Certificate Number : | 5-SHA-2022-17268168 | | |
| Inspection Date : | 25-07-2022 | | |
| Certificate Print Date : | 25-07-2022 | | |
| Services : | Registration Test | | |
| Vehicle Testing Partner : | Shamil | | |
| Vehicle Testing Center : | Shamil Al Qusais | | |
| Total Time Taken : | 7 min 27 sec | | |
| Appointment Ref Number : | -- | | |
| Start Time : | 13:05 | End Time : | 13:12 |
| Lane : | 04 | Token No. : | 193 |
| Attempt : | 1 | Prints No. : | 1 |

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)

| | | | |
|-------------------|------------------------|--------------------|---------------------------|
| | | | |
| 8700 KM | 896 L | 2814 AED | 2.2 ton |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

Parameter Readings

| | | | |
|---------------------------------------|--------------------------------------|---|------------------------------|
| Service brake imbalance on front axle | Service brake imbalance on rear axle | Parking brake imbalance between LHS and RHS | Vehicle on Petrol CO Reading |
| 5 % | 3 % | 3 % | 0.3 % |

Vehicle on Petrol HC

Reading
30 PPM VOL

Inspection Findings

Inspection Remarks:

FRONT LEFT SIDE FENDER/FRAME,BULKHEAD,CROSS MEMBER RADIATOR SUPPORT REPAIRED. UNDER MINOR ENGINE OIL LEAK .

Payment Details

| | | | |
|-------------------------|-------------------|--------------------|-------------------------------------|
| Inspection Performed by | Payment Method | Transaction Number | Service Fees |
| 19685 15741 | Cash | 17268168 | AED 170 Collected on 25/07/2022 |
| Parking Slot No | Service Name | Attempt | Received by |
| -- | Registration Test | 1 | Abdulrahman Mohammed Abdulrahman |

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يمتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

