





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20326385	Plate Category	: PRIVATE
Transaction Date	: 22 JUL 2020 11:17:44	Plate Number	: 313422 EA
Queue Number	: 199507	Import Doc. Ref.	:
Chassis Number	: 3GCUK9EC3EG313422	Manufacturer/Model	: CHEVROLET/SILVERADO
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: RED
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.03 - Number Plate Lights		انوار لوحة الأرقام
		LEFT SIDE NOT WORKING
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
		FRONT BOTH LOWER BALL JOINT & TIRE ROD END BOOTS WORNOUT
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.08 - Spare Tires		الاطار الاحتياطي
		SPARE TIRE REALEASE HOLE PLASTIC MOUNTING DETACH
05 Body		الهيكل
05.02 - Paint		الصنع
		PARTLY DENT/PAINT SCRTACHES
05.07 - Floor		الارضية
		RIGHT SIDE STEEPING BOARD PAD MISSING & RIGHT SIDE RUNNING BOARD DENT
05.08 - Chassis (Frame)		الشاصية
		RUSTY PAINTED RUSTFROOF
06 General Items		الاشياء العامة
06.09 - Mirrors Rear View		المرايا الداخلية
		SUN VISOR MIRROR CRACKED & COVER REMOVED
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		INSIDE FITTED WITH ROLL BAR
06.13 - Exhaust System		نظام العادم
		PIPE END CUT
06.14 - Transmission Condition		حالة ناقل الحركة
		JUDDERING WHEN CHANGING GEAR
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		OIL LEAK & WHITE SMOKE
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		204140 KM



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20326385	Plate Category	: PRIVATE
Transaction Date	: 22 JUL 2020 11:17:44	Plate Number	: 313422 EA
Queue Number	: 199507	Import Doc. Ref.	:
Chassis Number	: 3GCUK9EC3EG313422	Manufacturer/Model	: CHEVROLET/SILVERADO
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: RED
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.18 - A/C Not Cooling	A/C GAS LEAK/WIPER WASHER RESERVOIR CAP MISSING	عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	WARNING LIGHTS ON/SEAT BELTS LIGHTS ON	عطل في لوحة التحكم الالكتروني
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p>		

Test Certificate



FAILED

Plate Details :	--
Chassis No :	3GCUK9EC3EG313422
Vehicle Make :	CHEVROLET
Vehicle Model :	SILVERADO
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Marone
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	204142 Kms.
Origin : Mexico	Model Year : 2014
Gear Type : --	Engine Size : 6600 CC
Engine No : NIL	Horse Power : 195
Axles No : 2	Cylinders : 8
No Of Doors : 4	No Of Seats : 3
G. V. W. : 3130 Kgs.	Empty Weight : 2125 Kgs.

Certificate Number :	5-TAS-2020-12230673
Inspection Date :	26-07-2020
Certificate Print Date :	26-07-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	8 min 39 sec
Appointment Ref Number :	--
Start Time : 15:54	End Time : 16:02
Lane : 01	Token No. : 23
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 1%	Service brake imbalance on rear axle 8%	Parking brake imbalance between LHS and RHS 10%	Vehicle on Petrol CO Reading 10.32%
Vehicle on Petrol HC Reading 393 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Engine repair engine white smoke	Others (Major)	Major
Warning triangle	Missing	Major
Vehicle on Petrol CO Reading	CO reading more than 4.5%	Major

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	3	5	

Inspection Remarks: chassis & under body components rusty & painted