



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Nov 2022, 14:52:05
Transaction Number	18700677 (CC10006)	Queue Number	623448



Chassis Number	2C3CDYCJODH708534
Engine Number	
Vehicle Class	Car
Manufacturer	Dodge
Model	Challenger
Model Year	2013
Color	Black
Mileage	166346 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Chassis Condition		الشاسي
01.A Chassis Number	FRONT LEFT SIDE CHASSIS NUMBER STICKER PORTION DAMAGED	رقم القاعدة
01.B Chassis	FRONT BOTH SIDE CHASSIS & REAR LEFT SIDE CHASSIS EXTENSION REPAIRED	الشاسيه
02 Interior Condition		الحاله الداخليه
02.A AC Condition	OK	المكيف
03 Body		جسم المركبة
03.A Trunk	PORTION REPAIRED REPAINTED & REFITTED	صندوق
03.B Fenders	FRONT BOTH SIDE REFITTED & REAR BOTH SIDE PORTION REPAIRED, REPAINTED	مدكار
03.C Bonnet	REFITTED	غطاء المحرك
03.D Sign of back accident		وجود مؤشر لحادث في الخلف
03.E Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT, CROSSMEMBER , WHEEL ARCH REPAIRED	اخرى
03.F Floor	REAR BACK PANEL, COMPARTMENT ,QUATER PANEL WHEEL HOUSING, QUATER PANEL REPAIRED	الارضيه
03.G Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ

DEFECT	REMARKS	
03.H Vehicle Color	GRAY /SILVER	لون المركبة
03.I Sign of front accident		وجود مؤشر لحادث في المقدمة
03.J Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	JERKING & REFITTED	حالة الجير النظرى
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05.B Steering Oil	LEAK	زيت المقود
06 Engine Condition		المحرك
06.A Visual Engine Condition	SIGN OF LEAK & REFITTED, MISFIRING	حالة المحرك النظرى
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2018 CRACKED,	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2018 CRACKED,	الاطار الخلفي
08 Exhaust System		نظام العادم
08.A Modification	MODIFIED NOISY	تعديلات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Transfer Certificate :	64597968
Chassis No :	2C3CDYJC0DH708534
Vehicle Make :	DODGE
Vehicle Model :	CHALLENGER
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Black, Gray
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	166347 Kms.
Origin : Canada	Model Year : 2013
Gear Type : Automatic	Engine Size : 6200 CC
Engine No : 6135310470	Horse 470
Axles No : 2	Power :
No Of 2	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 2000 Kgs.	Empty 1700 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18204366		
Inspection Date :	29-11-2022		
Certificate Print Date :	29-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	15 min 56 sec		
Appointment Ref Number :	--		
Start Time :	9:14	End Time :	9:30
Lane :	03	Token No. :	110
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Vehicle Consumption (last 12 Months)

3359 KM	346 L	1180 AED	0.9 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 15 %	Service brake imbalance on rear axle 3 %	Parking brake imbalance between LHS and RHS 3 %	Vehicle on Petrol CO Reading 1.96 %
Vehicle on Petrol HC Reading 315 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Paint Change Color	Black , Gray	Gray , Silver	

Inspection Remarks:

back panel & rear both side frame member end repaired front both chassis,fender frames & bulk head frame repaired-passed as per previous history,minor dents & scratches on body

Payment Details

Inspection Performed by 6831	Payment Method Cash	Transaction Number 18204366	Service Fees AED 170 Collected on 29/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لتي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

