

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 40887140 (CC10006) Transaction Date

09 May 2022, 15:19:44

Queue Number

312309



Chassis Number **3GNEK18R8XG214417**

Engine Number

Vehicle Class Car

Manufacturer Chevrolet

Model Tahoe
Model Year 1999

Color Black

Mileage **326596 Km**

Fuel Type Petrol

No. Of Cylinders

Specification USA Imported

DEFECT REMARKS

01 Steering Condition		المقود
01.A Axel	LEFT SIDE AXLE BROKEN, RIGHT SIDE BOOT CUT	اكسلات
01.B Steering Oil	OIL LEAK	زيت المقود
01.C Tie Rod End	BOOT CUT	مؤخرة الرودات
01.D Steering Boot	BOOT CUT	ربلة المقود
02 Suspension System		ممتص الصدمات
O2.A Ball Joint	BOOT CUT	مفصل كروي
02.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
03 Brake Condition		الفرامل
03.A Brake Pedal	SPONGY & WEAK	دواسة الفرامل
O4 Body		جسم المركبة
04.A Bumper	FRONT BUMPER FRAME MISSING	دعامية
04.B Rusty	UNDER BODY PARTS & SUSPENTION, FLOOR, CHASSIS RUST PROOF & STILL GETTING RUSTY	صدأ
04.C Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES (CHANGE COLORE FROM WHITE TO BLACK)	الصبغ

DEFECT	REMARKS	
05 Chassis Condition		الشاصي
05.A Chassis	RIGHT SIDE MIDDLE & LEFT SIDE FRONT CHASSIS HAVE DENT SLIGHTLY BEND , THICK RUST PROOFED , STILL GETTING RUSTY	الشاسيه
06 Seats Condition		المقاعد
06.A Seat Belt	NOT WORKING	حزام الأمان
07 Exhaust System		نظام العادم
07.A Modification	MODIFIED,NOISY	تعديلات
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Interior Condition		الحاله الداخليه
09.A AC Condition	NOT WORKING	المكيف
09.B Sun Visor	LEFT SIDE MISSING	حاجب الشمس
09.C Door Panel	PORTION DAMAGED	لوحة بطانة الباب
09.D Roof Ceiling	LOOSE	بطانه السقف
09.E Dash Board	CENTER CONSOLE BOX COVER DAMAGED	لوحة القياده
10 Transmission Condition		الجير
10.A Road Test	NOT CHECK	فحص علي الطريق
10.B Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظرى
11 Engine Condition		المحرك
11.A Visual Engine Condition	OIL LEAK & REFITTED	حالة المحرك النظرى
11.B Other	OIL SUMB DENT	اخري
11.C Mount	OUNT RUBBER CRACKED	كرسي
12 Tires and Rims Condition		الاطارات
12.A Front Tyre	BOTH SIDE 2016 & EXPIRED, CRACKED	الاطار الامامي
12.B Rear Tyre	BOTH SIDE 2016 CRACKED & EXPIRED	 الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير سارى.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate











Plate Details: Chassis No: 3GNEK18R8XG214417 Vehicle Make: CHEVROLET Vehicle Model: TAHOE Vehicle Class: Light Vehicle **Body Type: JEEP** Fuel: Benzene Color: Black **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 3266028 Kms Origin: Model Year: 1999 6600 CC **Engine Size:** Gear Type: Automatic Engine No: Horse Power: 250 Axles No: Cylinders: No Of Doors: 2 No Of Seats: 6 G. V. W. : Empty Weight: 2146 Kgs. 3175 Kas.

Certificate Number:	5-TAS-2022-16749049				
Inspection Date :	11-05-2022				
Certificate Print Date:	12-05-2022				
Services :	Registration Test				
Vehicle Testing Partner:	Tasjeel				
Vehicle Testing Center:	Tasjeel Al Aweer				
Total Time Taken: 12 min 50 sec					
Appointment Ref Number:					
Start Time: 15:27	End Time: 15:40				
Lane: 02	Token No.: 203				
Attempt: 1	Prints No: 1				

Parameter Readings

Service brake imbalance on front axle 1%

<u>4</u>

Service brake imbalance on rear axle 45 %

Parking brake imbalance between LHS and RHS 54 % Vehicle on Petrol CO Reading 7.15 %

Vehicle on Petrol HC Reading 534 PPM VOL

Inspection Findings

Defects	Issue	Severity	
Tire	Date of manufactured tampered or expired	Major	
replace all tires/2016			
Steering Box	Continuous or excessive oil leak	Major	
Suspension kit replace front&rear suspension bushes,ball joints&rear	Others (Major) leaf spring bushes	Major	
Engine	Oil leaking continuously	Major	
Service brake imbalance on rear axle	More than 30% imbalance between L and RHS	More than 30% imbalance between LHS Major and RHS	
Axles	Excessive wear or worn out shaft toot spine	Excessive wear or worn out shaft tooth orMajor spine	
replace front left side axle shaft casing			
Vehicle on Petrol CO Reading	CO reading more than 4.5%	Major	
Axles replace front left axle shaft	Bend, twisted, fractured axle shaft	Major	
Battery fix bracket	Unsecure	Major	

Inspection Remarks: Both side middle chassis dent, chassis rust proofed, avoid under body floor & chassis getting rusty.

Payment Details

Inspection Performed by 32858 34944 Parking Slot No Payment Method Cash

Service Name

Registration Test

16749049

Attempt

Transaction Number 16749049 Service Fees

AED 170 Collected on 12/05/2022

Received by
Bajurdeen Abdul Gafoor

¹ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30.



This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.