



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>03 Jul 2022, 15:48:05</b>
Transaction Number	<b>38920971 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTJHY00W9D4110573</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Lexus</b>
Model	<b>LX 570</b>
Model Year	<b>2013</b>
Color	<b>White</b>
Mileage	<b>158483 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK & GRILL LOOSE	المكيف
01.B Air Bag	LEFT SIDE AIR BAG DAMAGED	وسائد هوائية
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.B Bonnet	REFITTED	غطاء المحرك
02.C Pillars	BOTH SIDE A/PILLAR OUTER PANEL REPAIRED,REPAINTED	القوائم
02.D Sign of front accident		وجود مؤشر لحادث في المقدمة
02.E Sign of side accident		وجود مؤشر لحادث في الجانب
02.F Floor	UNDER FLOOR THICK RUST PROOFED & TOO MUDDY	الارضية
02.G Other	FRONT BUMPER FRAME BULK HEAD FENDER REPAIRED	اخرى
02.H Fenders	FRONT FENDER REFITTED	مدكار
02.I Doors	FRONT LEFT SIDE REFITTED	أبواب
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري

DEFECT	REMARKS	
03.C DIFFERENTIAL	REAR MINOR OIL LEAK	الدفرنشيل
03.D Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Front Tyre	BOTH SIDE 2019 & RIGHT SIDE MINOR WORN OUT	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
04.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
05.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Other	STABILIZER LINK BOOT CUT	اخرى
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	FRONT LEFT SIDE RIGHT CHASSIS END REPAIRED , RIGHT SIDE END MOUNT RUSTY WEAK	الشاسيه
07.B Other	CHASSIS FRAME GETTING RUSTY	اخرى
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Possession Certificate :	66665544
Chassis No :	JTJHY00W9D4110573
Vehicle Make :	LEXUS
Vehicle Model :	LX 570
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White, Pearl
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	158486 Kms.
Origin : Japan	Model Year : 2013
Gear Type : Automatic	Engine Size : 5700 CC
Engine No : 3148480	Horse 388
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 8
G. V. W. : 2900 Kgs.	Empty 1600 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17141438		
Inspection Date :	04-07-2022		
Certificate Print Date :	04-07-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	8 min 24 sec		
Appointment Ref Number :	--		
Start Time :	14:10	End Time :	14:19
Lane :	03	Token No. :	181
Attempt :	1	Prints No. :	1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption (Rate in 12 Months)

16392 KM	1687 L	2733 AED	4.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 24 %	Service brake imbalance on rear axle 19 %	Parking brake imbalance between LHS and RHS 24 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 1 PPM VOL			

Inspection Remarks: LEFT SIDE FENDER FRAME/APRON REPAIRED /CHASSIS & UNDER BODY COMPOENETS PARTLY RUSTY

## Payment Details

Inspection Performed by 6831	Payment Method Cash	Transaction Number 17141438	Service Fees AED 170 Collected on 04/07/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

