



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>06 May 2022, 11:34:44</b>
Transaction Number	<b>42160887 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>SALLSAA346A921149</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Range Rover</b>
Model	<b>Sport</b>
Model Year	<b>2006</b>
Color	<b>White</b>
Mileage	<b>309059 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Sun Visor	BOTH SIDE COVER LOOSE	حاجب الشمس
01.B Other	CENTER CUP CONSOLE BOX SLIDING COVER MISSING	اخرى
01.C AC Condition	OK	المكيف
01.D Dash Board	CRACKED , LEATHER REPALCED	لوحة القيادة
01.E Mirror	LEFT SIDE FOLDING NOT WORKING	المرايا
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Doors	RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب
02.B Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
02.C Door Handle & Lock	FRONT LEFT SIDE OUTER HANDLE LOCK COVER MISSING	مقابض الأبواب والأقفال
02.D Fenders	REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
02.E Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES	الصبغ
02.F Trunk	PORTION REPAIRED,REPAINTED	صندوق
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
03.B Road Test	NOT CHECK	فحص علي الطريق

DEFECT	REMARKS	
03.C Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
<b>04 Steering Condition</b> <span style="float: right;">المقود</span>		
04.A Steering Oil	OIL LEAK	زيت المقود
<b>05 Suspension System</b> <span style="float: right;">ممتص الصدمات</span>		
05.A Other	STABLIZER MOTOR LEAK	اخرى
<b>06 Chassis Condition</b> <span style="float: right;">الشاسي</span>		
06.A Chassis	LEFT SIDE MIDDLE CHASSIS HAVE MINOR DENT	الشاسيه
<b>07 Tires and Rims Condition</b> <span style="float: right;">الاطارات</span>		
07.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>08 Engine Condition</b> <span style="float: right;">المحرك</span>		
08.A Visual Engine Condition	OIL LEAK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Transfer Certificate :	66427323
Chassis No :	SALLSAA346A921149
Vehicle Make :	RANGE ROVER
Vehicle Model :	SPORT
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	309063 Kms.
Origin :	Great Britain
Model Year :	2006
Gear Type :	Automatic
Engine Size :	5000 CC
Engine No :	010905B20...
Horse Power :	301
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	5
G. V. W. :	2850 Kgs.
Empty Weight :	2050 Kgs.

Certificate Number :	5-TAS-2022-16717758
Inspection Date :	09-05-2022
Certificate Print Date :	09-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 33 sec
Appointment Ref Number :	--
Start Time :	8:28
End Time :	8:38
Lane :	03
Token No. :	104
Attempt :	1
Prints No. :	1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption ( Rate last 12 Months )

16842 KM	1733 L	2808 AED	4.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 18 %	Service brake imbalance on rear axle 19 %	Parking brake imbalance between LHS and RHS 16 %	Vehicle on Petrol CO Reading 0.45 %
Vehicle on Petrol HC Reading 189 PPM VOL			

## Inspection Findings

Inspection Remarks: rear stabilizer actuator oil leak

## Payment Details

Inspection Performed by 59460 59460	Payment Method Cash	Transaction Number 16717758	Service Fees AED 170 Collected on 09/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

