

Queue Number

2761830

Transaction Date

18 Sep 2026, 16:58:55

Site Name

840 - Emirates Auctions

Transaction Number

48731728 (CC10009) (CC10012)



Vehicle Details

Chassis Number	VF37FNFU6K*****
Specification	GCC Specification
Make	Peugeot
Model	Partner
Model Year	2019
Color	White
Mileage	42444 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED DENTS SCRATCHES , PORTION RUSTY,HAILSTORM	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR FULLY MUDDY PORTION DENT RUSTY	الارضية
01.E Bumper	PORTION DAMAGED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Sign of front accident	FRONT BUMMPER FRAME BULK HEA DREPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED INNER BRACKET BEND, GETTING RUSTY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	SHAKING REFITTED GETTING RUSTY , BOLT MISSING	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED GETTING RUSTY BOLT MISSING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2022 CRACKED	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2022 , CRACK , RIGHT SIDE 2018 EXPIRED	الاطار الخلفي
05.C Spare Tire &Tools	TIRE MISSING	الاطار الاحتياطي و العدة
06 Wipers and Arms		المساحات
06.A Wiper Arm &Blade	RIGHT SIDE MISSING	ازرع المساحات والشفرات
07 Lights		الاضاءة
07.A Head Light	LENS GETTING FADED , RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE CRACK	الضوء الخلفي
07.C Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION GETTING RUSTY	اخرى
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
09.B Mirror	BOTH SIDE ADJUSTMENT NOT WORKING , CENTER MIRROR MISSING	المرآيا
09.C AC Condition	NOT COOLING , BUTTON NOT WORKING	المكيف
09.D Audio	LOOSE	صوتيات
09.E Dash Board	REFITTED , PANEL COVER PORTION LOOSE	لوحة القيادة
09.F Steering Wheel and control buttons	AIR BAG COVER REFITTED , EXTRA LEATHER	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	DUST COVER LOOSE	ذراع نقل السرعات
10 Battery Condition		حالة البطارية
10.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

