



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 Sep 2022, 14:54:10**
 Transaction Number **48478539 (CC10006)** Queue Number **595871**



Chassis Number **KMHGD41E1FU153482**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Hyundai**
 Model **Elantra**
 Model Year **2015**
 Color **Silver**
 Mileage **150591 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Sun Visor	RIGHT SIDE GLASS DAMAGED	حاجب الشمس
01.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.C Mirror	VIEW MIRROR LOOSE	المرايا
01.D AC Condition	OK & WINDOW ADJUSTER MISSING	المكيف
01.E Power Window Switch	FRONT LEFT SIDE NOT WORKING,BUTTON LOOSE	مفتاح النافذه
01.F Other	CENTER CONSOLE BOX LEATHER WORN OUT	اخرى
02 Lights		الاضاءة
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
02.B Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	REFITTED. JERKING.	حالة الجير النظرى
04 Body		جسم المركبة
04.A Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS	الصبغ

DEFECT	REMARKS	
	SCRATCHES	
04.B Sign of front accident		وجود مؤشر لحادث في المقدمة
04.C Fenders	FRONT REFITTED	مدكار
04.D Bonnet	REFITTED	غطاء المحرك
04.E Sign of back accident		وجود مؤشر لحادث في الخلف
04.F Bumper	FRONT BUMPER FRAME BULK HEAD RADIATOR SUPPORT REPAIRED & BUMPER FRAME BEND	دعامية
04.G Trunk	REPAIRED ,REPAINTED.	صندوق
04.H Other	REAR BUMPER FRAME BROKEN,RIGHT SIDE CRASH BOX DAMAGED	اخرى
04.I Floor	BOTH SIDE ROCK PANEL REPAIRED	الارضية
05 Engine Condition		المحرك
05.A Visual Engine Condition	MINOR OIL LEAK,REFITTED,VIBRATION	حالة المحرك النظرى
05.B Other	COOLING LEAKING FROM RADIATOR UPPER PIPE SIDE	اخرى
06 Seats Condition		المقاعد
06.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد
07 Battery Condition		حالة البطارية
07.A Battery bracket	MISSING	حامل البطارية
08 Steering Condition		المقود
08.A Axle	BOOT CUT,LEAK	اكسلات
09 Tires and Rims Condition		الاطارات
09.A Front Tyre	BOTH SIDE 2019 WORN OUT,CRACKED	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	REAR RIGHT SIDE LEAK	ممتص الصدمات
11 Chassis Condition		الشاسي
11.A Chassis	FRONT BOTH SIDE CHASSIS END MINOR DENT.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	KMHDG41E1FU153482
Vehicle Make :	HYUNDAI
Vehicle Model :	ELANTRA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	150595 Kms.
Origin : South Korea	Model Year : 2015
Gear Type : Automatic	Engine Size : 2000 CC
Engine No : g4nbeu9876...	Horse 140
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 1700 Kgs.	Empty 1450 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17722370		
Inspection Date :	27-09-2022		
Certificate Print Date :	27-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	10 min 3 sec		
Appointment Ref Number :	--		
Start Time :	9:54	End Time :	10:04
Lane :	03	Token No. :	118
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
2 %	4 %	24 %	0 %
Vehicle on Petrol HC Reading			
1 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Tire change all tires cracks & worn out	Cracked	Major
Stop lamps fix left side	Bulb busted	Major

Inspection Remarks: front & rear bumper support & crash box repaired

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
6831	Cash	17722370	AED 170 Collected on 27/09/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.