



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Nov 2021, 17:44:41
Transaction Number	32333593 (CC10006)	Queue Number	312309



Chassis Number	KMHD741C1LU026757
Engine Number	
Vehicle Class	Car
Manufacturer	Hyundai
Model	Elantra
Model Year	2020
Color	White
Mileage	61673 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
01.B Front Tyre	BOTH SIDE 2019/2021	الاطار الامامي
01.C Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
01.D Rims Condition	FRONT LEFT SIDE WHEEL COVER MISSING & NUT MISSING	حالة الجنوط
02 Body		جسم المركبة
02.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,BODY MINOR DENT,SCRATCHES	الصبغ
02.B Other	FRONT LEFT SIDE FENDER WHEEL HOUSING REPAIRED,DENT,CUT	اخرى
02.C Fenders	FRONT LEFT FENDER REPAINTED,PORTION REPAIRED	مدكار
02.D Doors	FRONT LEFT SIDE DOOR REPAINTEDPORTION REPAIRED ,MISALIGN	أبواب
02.E Floor	LEFT SIDE RUNNING BOARD REPAIRED&REAR BACK PANEL MINOR DENT&JOINT DETACHED &FRONT FIRE WALL PORTION DENT,DAMAGED	الارضية
02.F Bumper	REPAINTED,MISALIGN	دعامية
02.G Bonnet	REPAINTED&CABLE DAMAGED NOT CLOSING	غطاء المحرك
03 Chassis Condition		الشاصي

DEFECT	REMARKS	
03.A Chassis	FRONT LEFTSIDE CHASSIS BEND	الشاسيه
04 Suspension System		ممتص الصدمات
04.A Suspension Subframe	FRONT SUSPENSION SUB FRAME MOUNT DAMAGED,MISALIGN	
05 Engine Condition		المحرك
05.A Engine Condition	REFITIED&NOISY WHEN VEHICILE DRIVE	حالة المحرك
05.B Mount	RIGHT UPPER MOUNT BOLT MISALIGN&HAVE EXTRA MODIFIED RUBBER	كرسي
06 Transmission Condition		الجير
06.A Gear Box	OIL LEAK,REFITIED&SHIFTING LEVER BUTTON STUCK NOT WORKING &LEVER SHIFTING WITHOUT PRESS BUTTON	الجير
07 Seats Condition		المقاعد
07.A Seat Belt	FRONT BOTH SIDE NOT WORKING	حزام الأمان
07.B Seat Condition	DIRTY	حالة المقاعد
08 Interior Condition		الحالة الداخليه
08.A Air Bag	FRONT AIR BAG DAMAGED	وسائد هوائية
08.B AC Condition	NOT WORKING	المكيف
08.C Mirror	LEFT SIDE TRIANGLE COVER MISSING	المرايا
08.D Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم
09 Wipers and Arms		المساحات
09.A Wiper Arm &Blade	WORNOUT	ازرع المساحات والشفرات
10 Lights		الاضاءة
10.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
11 Exhaust System		نظام العادم
11.A Other	BRACKET BOLT MISSING	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	KMHD741C1LU026757
Vehicle Make :	HYUNDAI
Vehicle Model :	ELANTRA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	61674 Kms.
Origin :	South Korea
Model Year :	2020
Gear Type :	--
Engine Size :	2000 CC
Engine No :	G4FGKU9988
Horse Power :	140
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	1950 Kgs.
Empty Weight :	1450 Kgs.

Certificate Number :	5-TAS-2021-15495715
Inspection Date :	20-11-2021
Certificate Print Date :	20-11-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	15 min 39 sec
Appointment Ref Number :	--
Start Time :	15:58
End Time :	16:14
Lane :	01
Token No. :	185
Attempt :	1
Prints No. :	1

Parameter Readings

Service brake imbalance on front axle 27 %	Service brake imbalance on rear axle 2 %	Parking brake imbalance between LHS and RHS 2 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 0 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Park and Tail lamps REPAIR FRONT RIGHT SIDE PARK LIGHT	Defective	Major
Front Seat belts CHANGE FRONT BOTH SIDE BELT DAMAGE	Defective	Major
Spare Tire	Missing (Major)	Major

Inspection Remarks:

FRONT BULKHEAD/ BUMPER/FENDER/ BONNET&FRONT LEFT SIDE WHEEL HOUSING&RUNNING BOARD REPAIRED

Payment Details

Inspection Performed by 62439	Payment Method Cash	Transaction Number 15495715	Service Fees AED 170 Collected on 20/11/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

