



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Sep 2021, 14:18:48
Transaction Number	92491612 (CC10006)	Queue Number	312309



Chassis Number	1GCNK9E0XDZ108995
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	
Model Year	2013
Color	Red
Mileage	94719

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Rusty	UNDER BODY PARTS, CHASSIS FRAME GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COMPLETELY RUST PROOFED	الارضية
01.E Bumper	REPAINTED	دعامية
01.F Bonnet	PORTION REPAIRED, REPAINTED	غطاء المحرك
01.G Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD & CROSSMEMBER REPAIRED OLD GETTING RUSTY	اخرى
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FRAME COMPLETELY RUST PROOFED & FRONT BOTH SIDE END REPAIRED, RIGHT SIDE OUTER MIDDLE SLIGHTLY BEND	الشاسيه
03 Engine Condition		المحرك
03.A Mount	BUSHES CRACKED	كرسي
03.B Other	OK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Exhaust System		نظام العادم

DEFECT	REMARKS	
05.A Other	WELDED & REPAIRED	اخرى
06 Transmission Condition		الجير
06.A Gear Box	OK	الجير
07 Brake Condition		الفرامل
07.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
08 Wipers and Arms		المساحات
08.A Other	OK	اخرى
09 Lights		الاضاءة
09.A Head Light	OK	الاضاءة الرئيسية
09.B Other	OK	اخرى
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
10.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
11 Tires and Rims Condition		الاطارات
11.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
11.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
12 Interior Condition		الاجزاء الداخلية
12.A Other	OK	اخرى
12.B Mirror	OK	المرآيا
12.C AC Condition	OK	المكيف
13 Steering Condition		المقود
13.A Steering Boot	BOOT CUT & LEAKING	ربلة المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	12 69880 Abu Dhabi Private
Chassis No :	1GCNK9E0XDZ108995
Vehicle Make :	CHEVROLET
Vehicle Model :	SILVERADO
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Red
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	94722 Kms.
Origin :	United States
Model Year :	2013
Gear Type :	--
Engine Size :	6600 CC
Engine No :	NONE
Horse Power :	319
Axles No :	2
Cylinders :	8
No Of Doors :	2
No Of Seats :	5
G. V. W. :	Empty Weight : 2125 Kgs. 3130 Kgs.

Certificate Number :	5-TAS-2021-15057183
Inspection Date :	20-09-2021
Certificate Print Date :	20-09-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	21 min 30 sec
Appointment Ref Number :	--
Start Time :	13:45
End Time :	14:06
Lane :	01
Token No. :	159
Attempt :	1
Prints No :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



8611 KM
Distance per
year



887 L
Fuel consumed
per year



1437 AED
Fuel cost per
year



2.2 ton
Carbon footprint
per year

Parameter Readings

Service brake imbalance on front axle
3 %

Service brake imbalance on rear axle
2 %

Parking brake imbalance between LHS and RHS
2 %

Vehicle on Petrol CO Reading
0 %

Vehicle on Petrol HC Reading
2 PPM VOL

Inspection Remarks: front chassis end minor dent and bent/underneath chassis and component thick rust proofed

Payment Details

Inspection Performed by
33695

Payment Method
Cash

Transaction Number
15057183

Service Fees
AED 170 Collected on 20/09/2021

Parking Slot No
--

Service Name
Registration Test

Attempt
1

Received by
Sittu Paloth Sreesan Paloth

i This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

i Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

