

Queue Number 2877674

Transaction Date 16 Oct 2026, 16:15:33

Site Name
840 - Emirates AuctionsTransaction Number
25065349 (CC10009) (CC10025)

Vehicle Details

Chassis Number	SALVA2BG7G*****
Specification	GCC Specification
Make	Range Rover
Model	Evoque
Model Year	2016
Color	Silver
Mileage	95050 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT FIBER PAINT NOT CHECK REFITTED , REAR LEFT SIDE REPAINTED , REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED , REAR RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	REAR FLOOR JOINT RIGHT SIDE RUNNING BOARD REPAIRED	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED	دعامية
01.G Bonnet	PORTION REPAIRED REPAINTED , REFITTED	غطاء المحرك
01.H Pillars	RIGHT SIDE B / C / PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	FIBER PAINT NOT CHECK REFITTED , LUGGAGE SHADE MISSING	صندوق
01.J Sign of back accident	BACK PANEL QUARTER PANEL WHEELA RCH REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	REAR RIGHT SIDE CHASSIS & BOTH SIDE CHASSIS EXTENSION REPAIRED ,FRONT FULLY COVERED OILY CHECKED VISIBLE AREA ONLY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK PARTS REFITTED SHAKING GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DRIVER SEAT ADJUSTMENT NOT WORKING PROPERLY , REAR LOOSE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK PARTS REFITTED JERKING DELAY SHIFTING	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	RIGHT SIDE BOTH HUB COVER MSSING	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Wiper Arm &Blade	RONT PORTION DAMAGED	ازرع المساحات والشفرات
08 Lights		الاضاءة
08.A Head Light	LENS FADED , RIGHT SIDE BRACKET DMAGED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Brake Condition		الفرامل
09.A Brake Pedal	SPONGY	دواسة الفرامل
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
10.B AC Condition	OK	المكيف
10.C Audio	SCREEN PORTION FADED	صوتيات
10.D Dash Board	LEATHER PORTION LOOSE	لوحة القيادة
10.E Roof Ceiling	PORTION LOOSE	بطانه السقف
10.F Sun Visor	LEFT SIDE PORTION LOOSE	حاجب الشمس
10.G Door Panel	PORTION DAMAGED LOOSE	لوحة بطانة الباب
10.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11 Engine Cooling System		نظام تبريد المحرك
11.A Coolant tank	OIL WATER MIXED	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae