



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>22 Nov 2022, 16:13:10</b>
Transaction Number	<b>65008297 (CC10006)</b>	Queue Number	<b>627837</b>



Chassis Number	<b>MMBJNKA50DD022863</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	
Model Year	<b>2013</b>
Color	<b>White</b>
Mileage	<b>329561 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Transmission Condition</b>		<b>الجير</b>
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Visual Gear Box Condition	OK	حالة الجير النظرى
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	NOT WORKING	المكيف
02.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
03.B Fenders	REFITTED	مدكار
03.C Rusty	UNDER BODY PARTS, SUSPENTION, CHASSIS FRAME, FLOORING GETTING RUSTY	صدأ
03.D Bonnet	REFITTED	غطاء المحرك
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Mount	BUSHES CRACKED	كرسي
04.B Visual Engine Condition	OIL LEAK	حالة المحرك النظرى

DEFECT	REMARKS	
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Head Light	LENS FADED	الاضاءة الرئيسية
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Rear Tyre	BOTH SIDE 2020/2017 CRACKED EXPIRED	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2020 CRACKED	الاطار الامامي
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Steering Boot	BOOT CUT	ربلة المقود
07.B Tie Rod End	BOOT CUT	مؤخرة الروداد
<b>08 Chassis Condition</b>		<b>الشاصي</b>
08.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Arms	CONTROL ARM BUSHES CUT	ازرع
09.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
09.C Ball Joint	BOOT CUT	مفصل كروي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Possession Certificate :	67019370
Chassis No :	MMBJNKA50DDO22863
Vehicle Make :	MITSUBISHI
Vehicle Model :	L200
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	White, Trade name
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	359562 Kms.
Origin : Thailand	Model Year : 2013
Gear Type : Manual	Engine Size : 2400 CC
Engine No : 4G64AS3504	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 6
G. V. W. : 2600 Kgs.	Empty 1600 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18197712
Inspection Date :	28-11-2022
Certificate Print Date :	29-11-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	7 min 56 sec
Appointment Ref Number :	--
Start Time : 14:37	End Time : 14:45
Lane : 03	Token No. : 201
Attempt : 1	Prints No : 2

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption (Rate last 12 Months)

29132 KM	2998 L	10224 AED	7.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 4 %	Service brake imbalance on rear axle 12 %	Parking brake imbalance between LHS and RHS 10 %	Vehicle on Petrol CO Reading 0.5 %
Vehicle on Petrol HC Reading 133 PPM VOL			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Paint Change Color	White , Trade name	White	

Inspection Remarks: chassis & under body components partly rusty

## Payment Details

Inspection Performed by 6831 6831	Payment Method Cash	Transaction Number 18197712	Service Fees AED 170 Collected on 28/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Shawkat Mohamed Samir

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لتي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

