



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>05 Jan 2022, 17:45:28</b>
Transaction Number	<b>78487158 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>MROFX22G291316410</b>
Engine Number	
Vehicle Class	<b>Heavy</b>
Manufacturer	<b>Toyota</b>
Model	<b>Hilux</b>
Model Year	<b>2009</b>
Color	<b>White</b>
Mileage	<b>966861 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Doors	LEFT SIDE BOTH REPAIRED & REPAINTED	أبواب
01.B Floor	REAR CARRIOR BOX PORTION REPAIRED & REPAINTED	الارضية
01.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.D Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS , FLOOR GETTING RUSTY	صدأ
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
02.B Head Light	OK	الاضاءة الرئيسية
02.C Brake Light	RIGHT SIDE NOT WORKING	نور الفرامل
<b>03 Wipers and Arms</b>		<b>المساحات</b>
03.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK	المكيف
04.B Mirror	OK	المرايا
04.C Dash Board	INNER BOX COVER HOLDER LOCK DAMAGED	لوحة القيادة

DEFECT	REMARKS	
<b>05 Tires and Rims Condition</b>		الاطارات
05.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>06 Chassis Condition</b>		الشاصي
06.A Chassis	CHASSIS FRAME COMPLETELY RUSTY	الشاسيه
<b>07 Suspension System</b>		ممتص الصدمات
07.A Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED	ازرع
07.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
<b>08 Steering Condition</b>		المقود
08.A Steering Boot	BOOT CUT & LEAKING	ربلة المقود
08.B Steering Oil	OIL LEAK	زيت المقود

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	--
Chassis No :	MROFX22G291316410
Vehicle Make :	TOYOTA
Vehicle Model :	HILUX
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	966862 Kms.
Origin :	Thailand
Model Year :	2009
Gear Type :	Manual
Engine Size :	2694 CC
Engine No :	2TR6617606
Horse Power :	200
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1498 Kgs. 3080 Kgs.

Certificate Number :	5-TAS-2022-15857635
Inspection Date :	10-01-2022
Certificate Print Date :	10-01-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	13 min 46 sec
Appointment Ref Number :	--
Start Time :	13:21
End Time :	13:34
Lane :	03
Token No. :	182
Attempt :	1
Prints No :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
13 %	13 %	33 %	0.48 %
Vehicle on Petrol HC Reading			
102 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Dip beams(Low Beams) headlight CLEAN HEADLIGHT LENS	Lens cracked, broken or faded	Major
Steering Boots and Ball Joints REPLACE STEERING BOOT / CRACK	Worn-out or missing boot(s) (Major)	Major
Vehicle Floor REPAIR FLOOR MOUNTING RUSTY PORTIONS / WITHOUT PAINT FOR RECHECK	Damaged/heavily corroded	Major

## Inspection Remarks:

BODY MINOR SCRATCH & DENT / CHASSIS PORTIONS GETTING RUSTY, DO RUST PROOFING / MINOR ENGINE OIL LEAK /

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
74792	Cash	15857635	AED 170 Collected on 10/01/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.