



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **14 Nov 2022, 11:33:50**  
 Transaction Number **75275217 (CC10009)** Queue Number **622005**



Chassis Number **2T2ZK1BA3FC165175**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Lexus**  
 Model **RX 350**  
 Model Year **2015**  
 Color **Gold**  
 Mileage **70785 Miles**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **Imported**

DEFECT	REMARKS	
<b>01 Suspension System</b>		<b>ممتص الصدمات</b>
01.A Ball Joint	BOOT CUT	مفصل كروي
01.B Arms	LOWER ARM BUSHES CRACKED	ازرع
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Other	LEFT SIDE ROOF RAIL REPAINTED	اخرى
02.B Sign of side accident		وجود مؤشر لحادث في الجانب
02.C Sign of front accident		وجود مؤشر لحادث في المقدمة
02.D Fenders	FRONT BOTH SIDE , REAR LEFT SIDE REPAIRED REPAINTED , FRONT REFITTED	مدكار
02.E Doors	LEFT SIDE BOTH REPAIRED REPAINTED & REFITTED	أبواب
02.F Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
02.G Pillars	LEFT SIDE A/ PILLAR REPAIRED	القوائم
02.H Bonnet	PORTION REPAIRED REPAINTED & REFITTED	غطاء المحرك
02.I Floor	FLOOR PORTION LEFT SIDE REINFORCMENT ROCKER PANEL REPAIRED	الارضية
<b>03 Interior Condition</b>		<b>الحالة الداخليه</b>
03.A AC Condition	OK	المكيف

DEFECT	REMARKS	
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Mount	MOUNT RUBBER CRACKED	كرسي
04.B Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Visual Gear Box Condition	JERKING	حالة الجير النظري
05.B Gear Box Mount	MOUNT CRACK	كرسي الجير
05.C Road Test	NOT CHECK	فحص علي الطريق
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>07 Lights</b>		<b>الاضاءة</b>
07.A Tail Light	RIGHT SIDE CRACKED	الانارة
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2018 CRACKED,	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2018 CRACKED,	الاطار الخلفي
<b>09 Chassis Condition</b>		<b>الشاصي</b>
09.A Chassis	FRONT LEFT SIDE CHASSIS JOINT AREA REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	Y 38337 Dubai Private
Chassis No :	2T2ZK1BA3FC165175
Vehicle Make :	LEXUS
Vehicle Model :	RX 350
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Golden
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	113920 Kms.
Origin : Canada	Model Year : 2015
Gear Type : Automatic	Engine Size : 3500 CC
Engine No : NIL	Horse 279
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2500 Kgs.	Empty 1895 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18162578		
Inspection Date :	23-11-2022		
Certificate Print Date :	23-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	5 min 50 sec		
Appointment Ref Number :	--		
Start Time :	11:17	End Time :	11:23
Lane :	03	Token No. :	129
Attempt :	1	Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

14393 KM	1481 L	5051 AED	3.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 4 %	Service brake imbalance on rear axle 4 %	Parking brake imbalance between LHS and RHS 4 %	Vehicle on Petrol CO Reading 0.2 %
Vehicle on Petrol HC Reading 84 PPM VOL			

## Inspection Remarks:

FRONT LEFT SIDE CHASSIS REPAIRED HAVE DUBAI PASS CCM REPORT ATTACHED, FRONT LEFT SIDE BULK/HEAD,FENDER/FRAME, APRON ,A/PILLAR POST ,ROOF RAIL,WHEEL ARC, FLOOR ,ROCKER/PANEL REPAIRED.MINOR GEAR OIL LEAK

## Payment Details

Inspection Performed by 6831	Payment Method VTP Credit Account	Transaction Number 18162578	Service Fees AED 170 Collected on 23/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.