

## **TEST CERTIFICATE**

Site Number Transaction Number **840-Emirates Auctions** 64862832 (CC10008)

Transaction Date

07 Sep 2022, 16:25:44

**Oueue Number** 312309

Car

2016

Chassis Number

JTFLU71J8G7037307

**Engine Number** 

Vehicle Class

Manufacturer Toyota

Model **Land Cruiser** 

Model Year

Color Gold

Mileage

Fuel Type

No. Of Cylinders

Specification

352761 Km

Petrol

**GCC Specification** 

DEFECT REMARKS

**01 Seats Condition** المقاعد

01.A Seat Condition **SEAT DAMAGE** حالة المقاعد

**02 Exhaust System** 

03.A Front Tyre

**04 Suspension System** 

05.A Bumper

نظام العادم

02.A Other SILENCER MOUNDING LOOSE .EXCESSIVE PLAY.

الاطارات

الاطار الامامى

ممتص الصدمات

اخري

**03 Tires and Rims Condition** 

**BOTH SIDE 2021** 03.B Spare Tire &Tools MISSING الاطار الاحتياطي و العدة

03.C Rear Tyre **REAR BOTH SIDE 2020** الاطار الخلفي

04.A Leaf Spring **BUSHES CRACKED** 

05 Body جسم المركبة

FRONT GRILL DAMAGED , REAR SIDE COVER MISSING MISS

ALIGN.

05.B Floor BOTH SIDE BODY, MOUND BRACKET, REAR CABIN FLOOR

الارضية

**HEAVLY RUSTY** 

05.C Fenders REAR BOTH SIDE WHEELARCH LOWER AREA DENT.

مدكار

دعامية

DEFECT	REMARKS	
05.D Paint	BODY PORTION REPAIRED, REPAINTED . MINOR DENTS SCRATCHES ON BODY , PORTION RUSTY .	الصبغ
05.E Rusty	UNDER BODY ,FLOOR SUSPENSION PARTS RUSTY .	صدأ
05.F Windshield	SPOT CRACKED.	زجاج
06 Transmission Condition		الجير
06.A Propeller Shaft	FRONT ROMANO OIL LEAK	ناقل الحركة
06.B Visual Gear Box Condition	OIL WET	حالة الجير النظرى
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Chassis Condition		الشاصي
07.A Chassis	REAR CHASSIS CROSS MEMBERS BEND & CHASSIS FRAME RUSTY WEAK	الشاسيه
08 Engine Condition		المحرك
08.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
09 Steering Condition		المقود
09.A Tie Rod End	BALL JOINT BOOT CUT	مؤخرة الرودات
10 Interior Condition		الحاله الداخليه
10.A AC Condition	OK	المكيف
11 Lights		الاضاءة
11.A Brake Light	NOT WORKING	نور الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

## **Test Certificate**









Plate Details: Chassis No: JTFLU71J8G7037307 Vehicle Make: TOYOTA Vehicle Model: LAND CRUISER Vehicle Class: Light Vehicle **Body Type:** PICK-UP Fuel: Benzene Color: Golden **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 352762 Kms. Origin: Model Year: 2016 Engine Size: 5700 CC Gear Type: Manual Engine No: H125511 Horse 249 Power: Axles No: 2 Cylinders: 6 No Of No Of Seats: 3 Doors: 2600 Kgs. G. V. W. : Empty 1815 Kgs. Weight:

Certificate Number :	5-TAS-2022-17636926		
Inspection Date :	15-09-2022		
Certificate Print Date :	15-09-2022		
Services :	Registration Test		
Vehicle Testing Partner:	Tasjeel		
Vehicle Testing Center:	Tasjeel Al Aweer		
Total Time Taken:	18 min 45 sec		
Appointment Ref Number:			
<b>Start</b> 11:20	<b>End Time:</b> 11:39		
Time :	Token No.: 128		
<b>Lane:</b> 01	Prints No: 1		
Attempt: 1			

## **Parameter Readings**

Service brake imbalance on front axle

3 %

Reading 138 PPM VOL Service brake imbalance on rear axle 17 %

Parking brake imbalance between LHS and RHS  $19\,\%$ 

Vehicle on Petrol CO Reading 0.76 %

## Inspection Findings

Vehicle on Petrol HC

Defects	Issue	Severity	У	
Paint REPAIR ROOF FADED&RUSTY	Others (Major)	Major		
Rear registration plate lamps REPAIR REAR PLATE LAMP	Defective	Major		
Chassis CHANGE REAR CHASSIS CROSS MEMBER CRACK&RUSTY&C	Others (Major) Major  CRACK&RUSTY&CLEAN COMPLETE CHASSIS FOR RECHECK CRACK&RUSTY			
Doors and Locks REPAIR TAIL DOOR POST CRACK&RUSTY	Others (Major)	Major		
Vehicle Floor REPAIR BOTH SIDE RUNNING BOARD&FLOOR RUSTY	Others (Major)	Major		
Stop lamps REPAIR	Defective	Major	Major	
Seats REPAIR SEAT CUSHION&COVER DAMAGE	Others (Major)	Major		
Park and Tail lamps REPAIR TAIL LAMP&PARK LAMP	Defective	Major		
Direction-indicator lamps REPAIR BOTH SIDE REAR INDICATOR	Defective	Major	Major	
Engine REPAIR ENGINE OIL LEAK	Others (Major)	Major	Major	
Discrepancies	Old Value	New Value	Verified	

5700

**Inspection Remarks:** FRONT WIND SHIELD MINOR SPOT CRACK/ MINOR BODY PORTION DENT/ RUSTY&SCRATCHES

Payment Details
Inspection Performed by

3104

Engine Size Discrepancy in Engine Size

Payment Method
VTP Credit Account

Transaction Number 17636926

4000

Service Fees
AED 170 Collected on 15/09/2022

 Parking Slot No
 Service Name
 Attempt
 Received by

 - Registration Test
 1
 Bajurdeen Abdul Gafoor

170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
30. يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.