

Queue Number

2801712

Transaction Date

26 Sep 2026, 11:15:28

Site Name

840 - Emirates Auctions

Transaction Number

68118661 (CC10009) (CC10012)



Vehicle Details

Chassis Number	JN8AY2NY5E*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2014
Color	White
Mileage	128392 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION RUSTY	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS CHASSIS SUSPENSION GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT	الارضية
01.F Bumper	MODIFIED	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	BUTTON DAMAGED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME MISSING, BULK HEAD RADIATOR SUPPORT REPAIRED, FRONT LEFT SIDE FENDERS	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS OUTER PAINT WORN OUT, MOUNT BEND	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	OIL LEAK OPEN REFITTED, SHAKING GETTING RUSTY MUDDY, WIRING	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

Condition	Remarks	الحالة
04.A Seat Belt	MODIFIED , FRONT LEFT SIDE NOT WORKING	حزام الأمان
04.B Seat Condition	DAMAGED , EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY MUDDY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
07 Lights		الاضاءة
07.A Tail Light	FADED	الضوء الخلفي
07.B Fog light	RIGHT SIDE NOT WORKING	كشف الضباب
08 Suspension System		ممتص الصدمات
08.A Arms	BUSHES CRACKED	ازرع
08.B Other	SUSPENSION REFITTED	اخرى
08.C Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
09.B AC Condition	NOT COOLING	المكيف
09.C Dash Board	LEATHER REPLACED , PORTION LOOSE	لوحة القيادة
09.D Roof Ceiling	REFITTED	بطانه السقف
09.E Sun Visor	LEFT SIDE MISSING , RIGHT SIDE REPAIRED	حاجب الشمس
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

