

Queue Number 2840696

Transaction Date 06 Oct 2026, 15:00:48

Site Name
840 - Emirates AuctionsTransaction Number
84158221 (CC10013) (CC10025)

Vehicle Details

Chassis Number	ZARCABC41L*****
Specification	GCC Specification
Make	Alfa Romeo
Model	Gilulietta
Model Year	2020
Color	White
Mileage	136213 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DNT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION COVERED MINOR DENT	الارضية
01.F Bumper	MISALIGN HOOK COVER MISSING , REAR LEFT SIDE LIGHT COVER CRACK	دعامية
01.G Bonnet	REFITTED , SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	REPAINTED PORTION REPAIRED	صندوق
01.I Fuel Tank	OUTER COVER PART MISSING DAMAGED	خزان الوقود
01.J Sign of back accident	BACK PANEL , QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف

02 Chassis Condition

الشاسي

02.A Chassis	REAR LEFT SIDE EXTENSION DAMAGED REPAIRED DENT	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	-------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	-------------------------------------	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	2020 BOTH EXPIRED CRACKED	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2025 , RIGHT SIDE 2024	الاطار الخلفي
05.C Rims Condition	NUT MISSING	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
06.C Fog light	NOT WORKING	كشاف الضباب
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES MINOR DRY CRACK	ازرع
07.B Other	SUSPENSION PARTS REFITTED	اخرى
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	OK	المكيف
08.C Dash Board	WORN OUT	لوحة القيادة
08.D Sun Visor	RIGHT SIDE LOOSE	حاجب الشمس
08.E Door Panel	WORN OUT	لوحة بطانة الباب
08.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.G Sunroof	NOT WORKING MISALIGN	فتحت سقف
08.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
08.I Engine Start Button	REMOTE PORTION DAMAGED	زر تشغيل المحرك
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	WATER LEVEL LOW	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae