



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>06 Nov 2022, 14:58:54</b>
Transaction Number	<b>65751887 (CC10009)</b>	Queue Number	<b>617939</b>



Chassis Number	<b>SALVA2BG8EH878057</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Range Rover</b>
Model	<b>Evoque</b>
Model Year	<b>2014</b>
Color	<b>Black</b>
Mileage	<b>182519 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
01.B Front Tyre	BOTH SIDE 2021,	الاطار الامامي
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A Dash Board	LEATHER PORTION LOOSE	لوحة القيادة
02.B AC Condition	OK	المكيف
02.C Roof Ceiling	PORTION LOOSE	بطانه السقف
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Visual Engine Condition	OIL LEAK REFITTED	حالة المحرك النظري
03.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
04.C Other	STABILIZER LINK BOOT CUT	اخرى
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات

DEFECT	REMARKS	
05.B Steering Oil	MINOR OIL LEAK	زيت المقود
05.C Steering Boot	BOOT CUT	ربلة المقود
<b>06 Body</b>		<b>جسم المركبة</b>
06.A Sign of front accident		وجود مؤشر لحادث في المقدمة
06.B Floor	UNDER FLOOR CHASSIS FENDER FULLY COVERED CHECKED VISIBLE AREA	الارضية
06.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
06.D Fenders	FRONT FIBER PAINT CANNOT CHECK & REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
06.E Doors	RIGHT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب
06.F Trunk	FIBER PAINT CANNOT CHECK	صندوق
<b>07 Chassis Condition</b>		<b>الشاصي</b>
07.A Chassis	CHECKED VISIBLE AREA ONLY ,OK	الشاسيه
<b>08 Transmission Condition</b>		<b>الجير</b>
08.A Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظرى
08.B Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
08.C Road Test	NOT CHECKED	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.