



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	30 Oct 2022, 15:25:40
Transaction Number	99723737 (CC10009)	Queue Number	614518



Chassis Number	JTJHY00W494031660
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LX 570
Model Year	2009
Color	White
Mileage	123824 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Arms	LOWER ARM BUSHES CRACKED	ازرع
01.B Ball Joint	BOIOT CUT	مفصل كروي
02 Body		جسم المركبة
02.A Bonnet	REFITTED	غطاء المحرك
02.B Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.C Trunk	TRUNK AUTO NOT WORKING & REFITTED	صندوق
02.D Roof	REPAIRED REPAINTED	السقف
02.E Other	BODY SHAPE CHANGE TO NEW .MODEL	اخرى
02.F Sign of front accident		وجود مؤشر لحادث في المقدمة
02.G Sign of side accident		وجود مؤشر لحادث في الجانب
02.H Fenders	REFITTED	مدكار
03 Engine Condition		المحرك
03.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
03.B Mount	MOUNT CRACK	كرسي
04 Interior Condition		الحالة الداخليه

DEFECT	REMARKS	
04.A AC Condition	OK & GRILL PORTION DAMAGED	المكيف
04.B Mirror	SWITCH LOOSE.	المرايا
04.C Roof Light	COVER LOOSE	أنارة السقف
04.D Dash Board	CENETR CONSOLE BOX COVER CRACKED , SIDE COVER NOT CLOSE	لوحة القيادة
05 Transmission Condition		الجير
05.A Gear Box Mount	MOUNT CRACK	كرسي الجير
05.B Visual Gear Box Condition	JERKING, REFITTED	حالة الجير النظري
05.C Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2019 CRACKED,	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
07 Seats Condition		المقاعد
07.A Seat Condition	FRONT BOTH SIDE BACK COVER LOOSE & FRONT RIGHT SIDE SEAT ADJUSMENT NOT WORKING PROPERLY,BUTTON MISSING	حالة المقاعد
07.B Other	REAR BOTH SIDE NECK SEAT MISSING	اخرى
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
09 Lights		الاضاءة
09.A Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
09.B Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
10 Chassis Condition		الشاسي
10.A Chassis	FRONT BOTH SIDE CHASSIS END & REAR CROSS MEMBER REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	JTJHY00W494031660
Vehicle Make :	LEXUS
Vehicle Model :	LX 570
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	123825 Kms.
Origin : Japan	Model Year : 2009
Gear Type : Automatic	Engine Size : 5700 CC
Engine No : 3045650	Horse 388
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 8
G. V. W. : 3175 Kgs.	Empty 2200 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18084765		
Inspection Date :	12-11-2022		
Certificate Print Date :	12-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	16 min 35 sec		
Appointment Ref Number :	--		
Start Time :	14:36	End Time :	14:52
Lane :	01	Token No. :	178
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

7739 KM	797 L	2718 AED	2.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 19 %	Service brake imbalance on rear axle 17 %	Parking brake imbalance between LHS and RHS 9 %	Vehicle on Petrol CO Reading 0.05 %
Vehicle on Petrol HC Reading 3 PPM VOL			

Inspection Remarks: chassis rust proofed // face lifted old to new model // bulk head cut & modified //

Payment Details

Inspection Performed by 30544	Payment Method Cash	Transaction Number 18084765	Service Fees AED 170 Collected on 12/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

