



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **10 Mar 2023, 11:34:31**
 Transaction Number **47830883 (CC10009)** Queue Number **686492**



Chassis Number **WPOZZZ97ZBL004748**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Porsche**
 Model **Panamera**
 Model Year **2011**
 Color **White**
 Mileage **301192 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON IN DISPALY	ضوء تحذير
01.B Tail Light	BOTH SIDE CRACKED	الانارة
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK, PORTION GRILL DAMAGED , REAR BUTTON DAMAGED	المكيف
02.B Roof Ceiling	LOOSE	بطانه السقف
02.C Mirror	LEFT SIDE VIEW MIRROR GLASS GETTING FADED	المرايا
02.D Other	LEVER KNOB WORN OUT	اخرى
02.E Dash Board	WORN OUT	لوحة القيادة
02.F Door Panel	PORTION DAMAGED, SWITCH BUTTON MISSING	لوحة بطانة الباب
02.G Steering Wheel and control buttons	HORN MODIFIED	عجلة القيادة وازرار التحكم
03 Steering Condition		المقود
03.A Steering Boot	BOOT LEAK	ربلة المقود
03.B Axle	LEAK	اكسلات
03.C Steering Oil	OIL LEAK DRIPPING	زيت المقود
04 Body		جسم المركبة

DEFECT	REMARKS	
04.A Other	FRONT BOTH SIDE EXTENSION CUT MODIFIED , BUMPER FRAME CUT MODIFIED	اخرى
04.B Floor	BODY KIT MODIFIED , DENT, SCRATCHES (OILY, LEVEL LOW)	الارضية
04.C Bonnet	MODIFIED & REFITTED , SHOCK WEAK	غطاء المحرك
04.D Paint	BODY TOTALY REPAINTED REPAIRED MINOR DENT SCRATCHES	الصبغ
04.E Trunk	REFITTED	صندوق
05 Transmission Condition		الجير
05.A Gear Box Mount	MOUNT RUBBER CRACK	كرسي الجير
05.B Visual Gear Box Condition	JERKING , SIGN OF OIL LEAK	حالة الجير النظري
05.C Road Test	NOT CHECK	فحص على الطريق
05.D DIFFERENTIAL	BUSH RUBBER CRACK	الدفرنشل
06 Suspension System		ممتص الصدمات
06.A Ball Joint	BOOT CUT	مفصل كروي
06.B Shock Absorber	MODIFIED	ممتص الصدمات
06.C Other	BODY MODIFIED . LEVE; LOW	اخرى
06.D Arms	LOWER ARM BUSHES CUT	ازرع
07 Exhaust System		نظام العادم
07.A Other	PIPE CUT REWELDED	اخرى
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
08.B Other	EXTRA SPACER	اخرى
08.C Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
08.D Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
09 Seats Condition		المقاعد
09.A Seat Condition	FRONT BOTH SIDE SEAT COVER PORTION DAMAGED & LOOSE	حالة المقاعد
10 Engine Condition		المحرك
10.A Visual Engine Condition	OIL LEAK DRIPPING , REFITETD ABNORMAL NOISY	حالة المحرك النظري
10.B Mount	MOUNT RUBBER SIGN OF CRACK	كرسي
11 Chassis Condition		الشاسي
11.A Chassis	CHASSIS CHECKED VISIBLE AREA ONLY/OK (MUDDY & OILY)	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.