





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21138821	Plate Category	: PRIVATE
Transaction Date	: 16 SEP 2020 09:58:02	Plate Number	: 083725 EA
Queue Number	: 222009	Import Doc. Ref.	:
Chassis Number	: MHFBT9F34G6083725	Manufacturer/Model	: TOYOTA/YARIS
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.06 - Steering Wheel Alignment		ميراثية عجلة القيادة
	STEERING WHEEL OFF CENTER	
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
	BRAKE ROTORS RUSTY	
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
	FRONT TIRES DOT 2017 & 2016/ REAR TIRES DOT 2016 / CRACKS	
05 Body		الهيكل
05.02 - Paint		الصيغ
	BODY MINOR SCRATCHES & DENTS	
05.05 - Bumpers		الدعامية
	REPLACED & REFITTED	
05.08 - Chassis (Frame)		الشاصية
	FRONT LEFT SIDE MEMBER REPAIRED / RIGHT SIDE MEMBER END DENT	
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وثبيتها
	INTERIOR PARTLY WORN OUT/ DRIVER SEAT NO PROPER ADJUSTMENT	
06.14 - Transmission Condition		حالة ناقل الحركة
	OK	
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
	OK	
06.21 - Battery Condition		حالة البطارية
	BATTERY NOT SECURED	
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
	79348 KMS/ RADIO MALFUNCTION	
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
	FENDER BRACKETS/ BULKHEAD / RADIATOR SUPPORT REPAIRED/ FENDERS & BONNET REPLACED	



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21138821	Plate Category	: PRIVATE
Transaction Date	: 16 SEP 2020 09:58:02	Plate Number	: 083725 EA
Queue Number	: 222009	Import Doc. Ref.	:
Chassis Number	: MHFBT9F34G6083725	Manufacturer/Model	: TOYOTA/YARIS
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p>شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية</p>		

Test Certificate



✓ PASS

Vehicle
Registration



Transfer Certificate :	128200004542
Chassis No :	MHFBT9F34G6083725
Vehicle Make :	TOYOTA
Vehicle Model :	YARIS
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	79346 Kms.
Origin :	Indonesia
Model Year :	2016
Gear Type :	--
Engine No :	1NZZ434112
Engine Size :	1800 CC
Axles No :	2
Horse Power :	107
No Of Doors :	4
Cylinders :	4
G. V. W. :	1600 Kgs.
Empty Weight :	1100 Kgs.

Certificate Number :	5-MUT-2020-12534067
Inspection Date :	12-09-2020
Certificate Print Date :	17-09-2020
Services :	Registration Test
Vehicle Testing Partner :	Al Mutakamela Vehicle Testing LLC
Vehicle Testing Center :	Al Mutakamela Vehicle Testing Al Qouz
Total Time Taken :	9 min 55 sec
Appointment Ref Number :	--
Start Time :	20:56
End Time :	21:06
Lane :	06
Token No. :	692
Attempt :	1
Prints No. :	2

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



11335 KM

Distance per
year



806 L

Fuel consumed
per year



1306 AED

Fuel cost per
year



2.0 ton

Carbon footprint
per year

Parameter Readings

Service brake imbalance on
front axle
1 %

Service brake imbalance on
rear axle
15 %

Parking brake imbalance
between LHS and RHS
2 %

Vehicle on Petrol CO
Reading
0 %

Vehicle on Petrol HC
Reading
0 PPM VOL

Inspection Remarks:

REPAIR FRONT LEFT SIDE CHASSIS REPAIRED HAVING PASSED CCM REPORT TRANSACTION NO. 5-MUT-12527751 AS PER W/O 202009121 / FRONT FENDER FRAME RADIATOR SUPPORT BUMPER FRAME REPAIRED

Payment Details

Inspection Performed by
37060
70681

Payment Method
Cash

Transaction Number
12534067

Service Fees
AED 170 Collected on 12/09/2020

Parking Slot No
--

Service Name
Registration Test

Attempt
1

Received by
Waad Ali Abdullah Baakbah

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

