



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Jan 2023, 13:54:56
Transaction Number	92610319 (CC10010)	Queue Number	657779



Chassis Number	JTHBE262172009852
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	IS 350
Model Year	2007
Color	White
Mileage	001 Miles
Fuel Type	Petrol
No. Of Cylinders	6
Specification	Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Door Panel	PORTION MELTED	لوحة بطانة الباب
01.B AC Condition	NOT CHECK	المكيف
01.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
01.D Odometer reading	NOT CHECK	قراءة عداد المسافات
01.E Other	CENTER CONSOLE BOX DAMAGED	اخرى
01.F Dash Board	LEATHER REFITTED	لوحة القيادة
02 Body		جسم المركبة
02.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,PAINT PORTION DAMAGED,SPOT RUSTY	الصبغ
02.B Other	FRONT FENDER FRAME, BUMPER FRAME, RADITOR SUPPORT, BULK HEAD REPAIRED	اخرى
02.C Bumper	MISALIGN,PORTION DAMAGE	دعامية
02.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
02.E Floor	PORTION DENT,UNDER COVER MISSING .	الارضية
02.F Bonnet	REFITTED	غطاء المحرك
02.G Sign of front accident		وجود مؤشر لحادث في المقدمة

DEFECT	REMARKS	
02.H Fenders	FRONT REFITTED	مدكار
03 Transmission Condition		الجير
03.A Gear Box Mount	CRACKED	كرسي الجير
03.B Visual Gear Box Condition	NOT CHECK,REFITTED OIL LEAK	حالة الجير النظرى
03.C Road Test	NOT CHECK	فحص علي الطريق
03.D Propeller Shaft	MOUNTING BUSH CUT	ناقل الحركة
04 Exhaust System		نظام العادم
04.A Modification	EXHAUST MODIFIED	تعديلات
05 Suspension System		ممتص الصدمات
05.A Arms	LOWER ARM BUSH CUT	ازرع
05.B Shock Absorber	LEAK	ممتص الصدمات
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK,KEY MISSING,REFITTED OIL LEAK	حالة المحرك النظرى
06.B Other	ENGINE UPPER COVER DAMAGED	اخرى
06.C Mount	CRACKED	كرسي
07 Lights		الاضاءة
07.A Head Light	ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2019 CRACKED,	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الخلفي
09 Chassis Condition		الشاسي
09.A Chassis	FRONT LEFT SIDE CHASSIS LOWER PORTION MINOR DENT,DETACH	الشاسية
09.B Chassis Number	VIN NUMBER AREA DENT	رقم القاعدة
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	DAMAGED	خزان التبريد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

