

Queue Number 2869100

Transaction Date 15 Oct 2026, 12:32:14

Site Name
840 - Emirates AuctionsTransaction Number
30616954 (CC10026) (CC10026)

Vehicle Details

Chassis Number JN1CC11C09*****
 Specification GCC Specification
 Make Nissan
 Model Tiida
 Model Year 2009
 Color Silver
 Mileage 297532 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR LEFT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENTS SCRATCHES , PORTION FADED	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR THICK RUST PROOFED MIDOR DENT , MUDDY	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE FIXS BY SCREW , SCRATCHES	دعامية
01.G Windshield	REAR GLASS TINT FADED	زجاج
01.H Trunk	REPAINTED PORTION REPAIRED , MISALIGN	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS GETTING RUSTY , MUDDY OILLY	الشاسيه
--------------	-------------------------------------	---------

03 Engine Condition

المحرك

03.A Other	OIL PAN MINOR DENT	اخرى
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED PARTS REFITTED GETTING RUSTY , SIGN OF OIL WET , MUDDY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGE	حالة المقاعد
---------------------	----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED , PARTS REFITTED GETTING RUSTY, OIL LEAK DRIPING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2021 EXPIRED & RIGHT SIDE 2022 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
06.C Rims Condition	DENT SCRATCHES , PORTION RUSTY	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED , ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	BOTH SIDE DAMAGE	الضوء الخلفي
07.C Indicator & Hazard light	FRONT RIGHT SIDE INDICATOR HOUSING DAMAGE	الاشارات
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	BUSHES CRACKED	ممتص الصدمات
09 Interior Condition		الحالة الداخلية
09.A Other	CENTER CONSOLE BOX WORN OUT & INTERIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخرى
09.B Mirror	BOTH SIDE VIEW MIRROR HOUSING PORTION DAMAGE	المرآيا
09.C AC Condition	NOT CHECK	المكيف
09.D Roof Light	ROOF LIGHT SHADE POCKET DAMAGE	أنارة السقف
09.E Floor Matting	DIRTY	فرش الأرضية
09.F Dash Board	PORTION DAMAGE	لوحة القيادة
09.G Roof Ceiling	FABRIC PORTION LOOSE	بطانة السقف
09.H Sun Visor	BOTH SIDE MIRROR COVER DAMAGE & LEFT SIDE LOOSE	حاجب الشمس
09.I Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.K Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae