



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>08 May 2022, 17:24:17</b>
Transaction Number	<b>49824718 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>5FNYP48469B701494</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Honda</b>
Model	<b>Pilot</b>
Model Year	<b>2009</b>
Color	<b>Beige</b>
Mileage	<b>421483 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Suspension System</b>		<b>ممتص الصدمات</b>
01.A Other	STABILIZER LINK BOOT CUT	اخرى
01.B Arms	REAR CONTROL ARM BUSH CUT	ازرع
01.C Ball Joint	BOOT CUT	مفصل كروي
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Visual Gear Box Condition	OK	حالة الجير النظرى
02.B Propeller Shaft	RUBBER CUT	ناقل الحركة
02.C Road Test	NOT CHECK	فحص علي الطريق
02.D Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Rear Tyre	BOTH SIDE 2019 BADLY CRACKED , WORN OUT	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2020 CRACKED , WORN OUT	الاطار الامامي
03.C Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
03.D Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
<b>04 Steering Condition</b>		<b>المقود</b>
04.A Steering Oil	OIL LEAK	زيت المقود

DEFECT	REMARKS	
04.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
04.C Axle	BOOT CUT	اكسلات
<b>05 Lights</b>		<b>الاضاءة</b>
05.A Head Light	LENS FADED	الاضاءة الرئيسية
<b>06 Interior Condition</b>		<b>الحالة الداخليه</b>
06.A AC Condition	NOT COOLING	المكيف
<b>07 Body</b>		<b>جسم المركبة</b>
07.A Fenders	FRONT BOTH SIDE REPAIRED,REPAINTED & REFITTED & REAR RIGHT SIDE PORTION REPAIRED,REPAINTED	مذكار
07.B Paint	BODY PORTION REPAIRED,REPAINTED & MINOR DENT SCRATCHES & PORTION FADED, RUSTY	الصبغ
07.C Doors	FRONT BOTH SIDE REPAINTED,PORTION REPAIRED	أبواب
07.D Trunk	PORTION REPAINTED	صندوق
07.E Bumper	MISALIGN	دعامية
07.F Other	FRONT FENDER FRAME, RADITOR SUPPORT REPAIRED	اخرى
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	OK	الشاسيه
<b>10 Seats Condition</b>		<b>المقاعد</b>
10.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.