



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	21 Apr 2022, 14:19:57
Transaction Number	45102989 (CC10008)	Queue Number	312309



Chassis Number	2G1175S34E9150235
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Impala
Model Year	2014
Color	White
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED,REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.B Other	FRONT FENDER FRAME,APRON WHEEL HOUSING ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
01.C Floor	FRONT LEFT SIDE RUNNING BOARD REPAIRED	الارضية
01.D Pillars	FRONT SIED A/PILLAR&LEFT SIDE B/PILLAR ,ROCKER ROCKER PANEL REPAIRED	القوائم
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
01.G Doors	FRONT LEFT SIDE DOOR HING HOLDER MISSING	أبواب
02 Interior Condition		الحالة الداخلية
02.A Odometer reading	ODOMETER NOT SHOWING	قراءة عداد المسافات
02.B AC Condition	OK	المكيف
02.C Door Panel	FRONT LEFT SIDE DAMAGED	لوحة بطانة الباب
02.D Power Window Switch	MAIN SWITCH LOOSE	مفتاح النافذة
02.E Steering Wheel and control buttons	AIR BAG UNIT DAMAGED&CONTROL BUTTON NOT WORKING	عجلة القيادة وازرار التحكم
03 Lights		الاضاءة

DEFECT	REMARKS	
03.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2021 WORNOUT	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
04.C Rims Condition	FRONT RIGHT SIDE WELDED REPAIRED	حالة الجنوط
05 Chassis Condition		الشاصي
05.A Chassis	FRONT LEFT SIDE CHASSIS END REPAIRED,CHASSIS MINOR BEND	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	OIL LEAK	حالة المحرك النظري
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	OK	حالة الجير النظري
07.B Road Test	NOT CHECK	فحص علي الطريق
08 Battery Condition		حالة البطارية
08.A Battery bracket	VEHICLE COMPUTER FIXED BY WIRE	حامل البطارية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Plate Details :	--
Chassis No :	2G1175S34E9150235
Vehicle Make :	CHEVROLET
Vehicle Model :	IMPALA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	273574 Kms.
Origin :	Canada
Model Year :	2014
Gear Type :	Automatic
Engine Size :	6000 CC
Engine No :	1E9150235
Horse Power :	220
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1500 Kgs. 2000 Kgs.

Certificate Number :	5-TAS-2022-16702618
Inspection Date :	29-04-2022
Certificate Print Date :	29-04-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	10 min 39 sec
Appointment Ref Number :	--
Start Time :	23:23
End Time :	23:33
Lane :	02
Token No. :	220
Attempt :	1
Prints No. :	1

Carbon footprint



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

24870 KM	2560 L	4148 AED	6.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
9 %	10 %	13 %	0.25 %

Vehicle on Petrol HC Reading

38 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	6000	3600	

Inspection Remarks:

Front left side chassis repaired,ok by ccm wo#2022-04-29-5,bulk head,bumper frame,fender frame,front both side chassis outer skirt repaired.

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
34944	Cash	16702618	AED 170 Collected on 29/04/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لتي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

